



Release Notes  
Polycom® Video Border Proxy (VBP™)  
VOS Version 11.2.12

---

<b>Trademark Information</b> .....	<b>2</b>
<b>Introducing the Polycom VBP System Version 11.2.12</b> .....	<b>3</b>
<b>What's New in the Polycom VBP System Version 11.2.12</b> .....	<b>3</b>
<b>Out of the Box Installation notes</b> .....	<b>4</b>
<b>Interoperability</b> .....	<b>4</b>
<b>Known Issues</b> .....	<b>5</b>
<b>Installation Recommendation</b> .....	<b>7</b>
<b>New Features introduced in VOS 11.2.12</b> .....	<b>7</b>
<b>Fixes and Enhancements in VOS 11.2.12</b> .....	<b>9</b>
<b>New Features introduced in VOS 11.2.10</b> .....	<b>13</b>
<b>Fixes and Enhancements in VOS 11.2.10</b> .....	<b>14</b>
<b>New Features introduced in VOS 11.2.6</b> .....	<b>17</b>
<b>Fixes and Enhancements in VOS 11.2.6</b> .....	<b>19</b>
<b>New Features introduced in VOS 11.2.3</b> .....	<b>21</b>
<b>Fixes and Enhancements in VOS 11.2.3</b> .....	<b>22</b>
<b>New Features introduced in VOS 9.1.5.3</b> .....	<b>24</b>
<b>Fixes and Enhancements in VOS 9.1.5.3</b> .....	<b>28</b>
<b>New Features introduced in VOS 9.1.5.2</b> .....	<b>31</b>
<b>Fixes and Enhancements in VOS 9.1.5.2</b> .....	<b>31</b>
<b>New Features introduced in VOS 9.1.5.1</b> .....	<b>32</b>
<b>Fixes and Enhancements in VOS 9.1.5.1</b> .....	<b>32</b>
<b>New Features introduced in VOS 9.1.5</b> .....	<b>32</b>
<b>Fixes and Enhancements in VOS 9.1.5</b> .....	<b>33</b>
<b>New Features introduced in VOS 9.1.4</b> .....	<b>34</b>
<b>Fixes and Enhancements in VOS 9.1.4</b> .....	<b>34</b>
<b>New Features introduced in VOS 9.1.3</b> .....	<b>35</b>
<b>Fixes and Enhancements in VOS 9.1.3</b> .....	<b>35</b>
<b>New Features introduced in VOS 8.11.1</b> .....	<b>35</b>
<b>Fixes and Enhancements in VOS 8.11.1</b> .....	<b>35</b>
<b>New Features introduce in VOS 8.9.1</b> .....	<b>36</b>
<b>Fixes and Enhancements in VOS 8.9.1</b> .....	<b>36</b>
<b>Upgrade Instructions</b> .....	<b>38</b>
<b>Upgrade procedure</b> .....	<b>38</b>
<b>Obtaining Further Assistance</b> .....	<b>38</b>

## Trademark Information

Polycom®, the Polycom “Triangles” logo, and the names and marks associated with Polycom’s products are trademarks and/or service marks of Polycom, Inc., and are registered and/or common-law marks in the United States and various other countries. All other trademarks are the property of their respective owners.

© 2012 Polycom, Inc. All rights reserved.

Polycom, Inc.  
4750 Willow Road  
Pleasanton, CA 94588-2708  
USA

No part of this document may be reproduced or transmitted in any form or by any means, electronic or mechanical, for any purpose, without the express written permission of Polycom, Inc. Under the law, reproducing includes translating into another language or format. As between the parties, Polycom, Inc., retains title to and ownership of all proprietary rights with respect to the software contained within its products. The software is protected by United States copyright laws and international treaty provision. Therefore, you must treat the software like any other copyrighted material (e.g., a book or sound recording).

Every effort has been made to ensure that the information in this document is accurate. Polycom, Inc., is not responsible for printing or clerical errors. Information in this document is subject to change without notice.

---

## **Introducing the Polycom VBP System Version 11.2.12**

This document describes the enhancements and fixes provided by the Polycom Video Border Proxy (VBP) VoIP Operating System (VOS), version 11.2.12. This document includes all modifications made since VBP VOS version 7.2.2

### **What's New in the Polycom VBP System Version 11.2.12**

The Polycom VBP system version 11.2.12 is a full all platforms release that resolves customer issues found in the field.

H.323 Whitelist/Black feature modification.

FQDN support for VBP-E LAN-side gatekeeper mode

Support for a 50Mbps license key

## Out of the Box Installation notes

When installing the VBP-E system for the first time, the systems DHCP server is enabled and serving out an IP address range of 192.168.1.150 – 192.168.1.199 to your computer dynamically. By default the systems DHCP server does NOT assign default DNS server information. After configuring the Network parameters e.g WAN IP Address, Default gateway, Primary and Secondary DNS servers the system will now assign these DNS server IP addresses to the DHCP server. If you're configuring the VBP system for a dynamic WAN type, check the DHCP server page after you have configured the Network parameters for the presence of DNS server IP addresses received from the provider's server.

For testing Internet connectivity you will need to renew your computers DHCP address to receive valid DNS server information. You can disable/enable your network adapter, disconnect and reconnect your Ethernet cable, or from a command prompt on a Windows OS type ipconfig -release then ipconfig -renew.

After you verify your computer now has valid Primary and Secondary DNS server IP addresses you will now be able to open a web browser and verify Internet browsing.

## Interoperability

- Polycom CMA 4000/5000 system v4.01.02 or higher (see note)
- Polycom V and VSX Series v8.7.1 or higher
- Polycom ViewStation SP/MP/512/H.323 v7.5.4
- Polycom PVX v8.0.2 or higher
- Polycom ViewStation FX/EX/4000 v6.0.5
- Polycom HDX systems v2.0.3.1 or higher
- Polycom QDX 6000 (all versions)
- Polycom MGC v8.0.2 or higher
- Polycom RSS2000 v3.0.2 or higher
- Polycom RMX 2000 v3.0 or higher
- Polycom RMX 1000 (all versions)
- Polycom DMA 7000 v1.0 or higher
- Polycom RealPresence Resource Manager v7.0.0 or higher
- Polycom RealPresence Mobile v1.0 or higher

Note: The following issues, which may impact VBP functionality exists in CMA 4.01.02. These issues are addressed in CMA version 4.01.04

- Duplicate Aliases – When a CMA Desktop or HDX in VC2/dynamic mode moves from an internal CMA connection to an external VBP Access Proxy connection you might experience a scenario where the endpoint cannot connect to the CMA Server. An HDX endpoint is likely in this state if it displays an indicator stating that the gatekeeper service is down. A CMAD client is likely in this state if cannot progress beyond the “signing into the media server” message. In some cases, gracefully logging out of the internal location and waiting at least 10 minutes before an external login can reduce the chances of experiencing this issue.

- Dual Redundancy – When deploying 2 VBP systems and 2 CMA server's for what is called Dual Redundancy, if the MASTER CMA server fails, this forces the BACKUP CMA server to have control of all services, it is possible when this CMA failover happens, this CMA server may NOT send responses from the VIP (virtual IP) causing messages to be sent from the physical IP, the VBP is expecting messages to come from the VIP and will not be forwarded to the remote client. When deploying Single Redundancy 2 VBP systems and 1 CMA server, if the MASTER VBP fails, the BACKUP VBP will take over and function as expected.

## Known Issues

- 9543 – Certificates – The system includes two embedded root certificate authorities, VeriSign and Go-Daddy. VBP VOS 11.2.12 includes a security update to the OpenSSL module, reference issue 9246 below, the VeriSign root CA was integrated and the Go-Daddy root CA was not during this update. The Go-Daddy root CA support will be available in next VBP HOTFIX available through PGS. You may install a Go-Daddy signed certificate for the supported system applications however a scan of the system may report a certificate chaining issue with the Go-Daddy signed certificate
- H.460 – NAT router issue - When deploying H.460 device behind a 2 Wire NAT router calls will fail – there is no stable work around at this time for deploying a H.460 device behind a 2 Wire system that is running a factory default configuration. It may be possible to configure the 2 Wire NAT systems which will allow the H.460 device to have successful calls. 4670 outlined below is an attempt at bypassing the 2 Wire ALG by assigning an alternate Q.931 port, however has not proven 100% successful at this time. 4670 has proven success in other scenarios where H.460 calls using the default TCP 1720 port where failing. Polycom engineering is continuing to investigate a solution for this issue.
- 5479 - VIU-183 – ViewStation FX and H.460 clients. With the FX and H.460 client registered to the same VBP-ST, one way media may occur in either direction.
- 5967 – ESCVIU-45 – GUI – VBP now calculates the correct bandwidth usage even after the H323 End Point down speeds during a call setup. The following mode is still outstanding and will be fix in a later release: LAN side Gatekeeper VBP-E
- 6625 – ESCVIU-64 – H.323 – WAN-Side Gatekeeper mode does not support the usage of a DNS entry, the system must have a IP address in the field.
- 5823 – ESCVIU-51 – H.323 – Lifesize Multi-point endpoints version 4.7.0 registered to the VBP Embedded Gatekeeper dialing 2 public IP endpoints. When the first endpoint being called is a Lifesize and the second endpoint is an HDX or any H.323 endpoint, the call fails to complete to the seconds endpoint. The second call is also being sent to the first endpoint – issue – When the Lifesize endpoint registered to the Embedded gatekeeper creates a port 1720 TCP connection to the first endpoint for call control, the call completes with audio and video as expected. When the second call is placed the Lifesize endpoint re-uses the same 1720 TCP connection for the second call and causes the VBP to send the SETUP to the first endpoint. When replacing the first endpoint with a HDX or other H.323 endpoint the issue does not exist. This issue is between Lifesize endpoints only, lifesize has been contacted about this issue and will be providing a fix to the endpoint code base.

- 7570 – H.323 – H.245 sockets in listen state – When the system receives a call and processes the H.225 Q.931 message with a CONNECT, the system assigns the H.245 port to the called and calling system. If the called system hangs up before creating the TCP connection to the assigned H.245 port 14085 – 15084 the system will continue to listen for a TCP connection on this port. Over time. If the error condition continues it's possible that calls will fail to be processed by the system and a system reboot will be necessary. This error only happens when a calling system fails to create a TCP connection for H.245 negotiation. Example: When a H.323 call is initiated and hangs up immediately i.e. within 1 second it's possible the system will have a H.245 port assigned and will be in listen state.

```
# netstat -napt
```

```
Active Internet connections (servers and established)
```

Proto	Recv-Q	Send-Q	Local Address	Foreign Address	State	PID/Program name
tcp	0	0	12.48.260.10:14317	0.0.0.0:*	LISTEN	3373/mand
tcp	0	0	12.48.260.10:14445	0.0.0.0:*	LISTEN	3373/mand

## Installation Recommendation

Platform	Upgrade Recommendation	Comment
All Platforms	All Platforms	This release will replace any Polycom version with a version string greater than 9.1.5.1.
	Security update included	This release includes an SSL daemon security update to OpenSSL v1.0.1c
		This release is recommended for systems configured as VBP-E 2 Hop with access proxy enabled.

## New Features introduced in VOS 11.2.12

- 7881 – H.323 – VBP-E – FQDN support for LAN-side Gatekeeper Mode – The system now supports entering an FQDN or an IPv4 address as the LAN-side gatekeeper address. When an FQDN address is configured the system will perform an h323\_cs SRV query then, A record query to resolve the FQDN. If the FQDN is entered incorrectly or the systems DNS server is unavailable the following Activity log message will be displayed;

H.323 activity logs (newest on top)		
Event/Time	Source	Destination
Gatekeeper reachability Jul 28 22:19:39	Unable to Resolve GK FQDN Reason: DNS Lookup Fail FQDN: abc.example.com Result: No GK Address Available	
Gatekeeper reachability Jul 28 22:19:22	Unable to Resolve GK FQDN Reason: DNS Lookup Fail FQDN: abc.example.com Result: No GK Address Available	



The system performs a query at 15 second intervals for the configured FQDN, with a successful A record response the system will use the first priority 1 A record address to forward H.323 calls. If the DNS server becomes unreachable after a successful lookup has occurred the system will continue to use the last known priority 1 A record address until the DNS server becomes reachable.

- 8823 – License Key – H.323 – Added support for a 50Mbps license key
- 9053 – ESCVIU-98 – H.323 – VBP-E LAN-side gatekeeper mode – When receiving an ANNEX O dialed string e.g. user@host on the WAN interface the system previously modified the message and forwarded only the user portion to the configured gatekeeper address for call processing. The following check box has been added to the LAN-side gatekeeper mode settings to allow the full unresolved ANNEX O string to be sent as received to the gatekeeper for call processing.

#### Send Unmodified Dial String to Gatekeeper

- 9206 – ESCVIU-98 – H.323 - VBP-E LAN-side gatekeeper mode or Embedded gatekeeper mode – In pre 11.2.x version of VBP VOS when the user dialed string of user@host was dialed by a LAN side endpoint behind a VBP the system would modify the string and only send the user portion to the destination system. Post 11.2.x VBP VOS will send the full ANNEX O string to the destination system as it was dialed by the LAN side endpoint. Noted in VOS release 11.2.6 with issue 6934 the older VBP VOS 7.2.2 configured as Embedded gatekeeper was unable to provide call processing when the full unresolved ANNEX O string was received. In certain solutions with older VBP VOS it may be desired to revert the outbound ANNEX O user@host string to be modified and sent as the user portion only. This option is only needed when dialing ANNEX O destinations to VBP VOS 7.2.2 from VBP VOS 11.2.x systems.

By enabling the following option the system will modify the outbound ANNEX O string to only send the user portion to the destination system.

#### Send parsed ANNEX O string Outbound

## Fixes and Enhancements in VOS 11.2.12

- 8656 – H.323 – Whitelist/Blacklist - VBP-ST – Enhanced the existing feature to support Polycom dynamic mode endpoints. When the system is configured for Whitelist Static/Dynamic all H.323/H.460 requests to UDP port 1719 and TCP port 1720 will be dropped unless defined.

Dynamic mode endpoints are supported today through the Access Proxy, this feature enhancement now includes automatic UDP 1719 and TCP 1720 rule insertion from these authorized endpoint source IP's for registration and call setup. All other source IP's will be dropped. When supporting H.323/H.460 endpoints that do not support dynamic mode authorization a Whitelist-Static entry must be entered.

When enabling the Whitelist Static/Dynamic operation mode, the system automatically adds currently authorized dynamic mode endpoints to the rules. Static entries will need to be added manually for non-dynamic mode endpoints.

Adding a Whitelist or Blacklist static entry will not disrupt ongoing calls.

The feature now supports changing from Disabled to Whitelist Static/Dynamic or any combination of setting without disrupting current calls.

The ability to add a Whitelist/Blacklist static entry for a DNS name is not supported with this release.

### H.323 Whitelist/Blacklist [Help](#)

The whitelist/blacklist feature is used to block H.323 calls to this system based on IP addresses.

**Whitelist:** When selected all H.323 devices are blocked by default. Only devices in the whitelist are allowed.

**Blacklist:** When selected all H.323 devices are allowed by default. Devices listed in the blacklist are blocked.

**NOTE:** The Firewall must be enabled for this feature to function.

Select list type:

- Disabled  
 Blacklist  
 Whitelist Static-Only  
 Whitelist Static/Dynamic

Whitelist-Static	
Select: <a href="#">All</a> <a href="#">None</a>	Action: <input type="button" value="Delete"/>
	Address
The list is currently empty	

#### Add a new Whitelist-Static entry

Address:

Whitelist-Dynamic	
	Address
The list is currently empty	

- 9304 - H.323 – Whitelist/Blacklist – Modified the feature to accept a bit mask when configuring a static entry. The static entry can now be configured as a host addresses e.g. a.b.c.d or subnet in bit mask format a.b.c.d/xx.
- 8540 – ALG - H.323 – TLS Proxy - DMA interoperability – Destination IP only calls from DMA when the VBP-E is configured in TLS Proxy mode e.g. when the user dials an IPv4 only call destined for a public IP endpoint via the DMA configured VBP-E system used for B2B calling the call will fail to be processed correctly by the VBP-E system. This issue is now resolved.
- 9246 – Security – OpenSSL – Updated OpenSSL to version 1.0.1c to address the following CVE's
  - CVE-2011-3389 - SSLv3.0/TLSv1.0 Protocol Weak CBC Mode Vulnerability
  - CVE-2011-1923 - SSL/TLS server accepts a weak Diffie-Hellman public value
  - CVE-2012-2333 - OpenSSL Security Advisory 20120510
- 6384 – VoIP Traversal – VoIP traversal Firewall – Added additional fields to the VoIP Traversal Firewall settings. The system can now support the ability to add a port range, and packet type (TCP/UDP/ANY) to VoIP Traversal firewall rules. Additional error checking was added to help prevent duplicates, and to verify the port range is correct.
  - 6909 – VoIP Traversal – VoIP traversal Firewall – Added warning messages, and disallowed enabling the VoIP Traversal Firewall if the main system firewall is off. Added a warning message on the main system firewall page, and the VoIP Traversal Firewall page, if the main system firewall is off, and the VoIP Traversal firewall is on. Also, if both are off, the VoIP Traversal firewall can no longer be enabled until the main firewall is back on.
- 8189 – VoIP Traversal – VoIP traversal Firewall – If a port was specified when adding VoIP traversal firewall rule the rule would not be added correctly in iptables.
- 9239 – VoIP Traversal – Remote client – The VBP-E configured as a VoIP Traversal remote client allows a LAN side device to request DHCP to obtain a VoIP Traversal network IP address. The LAN side device did not receive the correct routes in the DHCP offer.
- 9010 – Security – VBP-ST – The UI option to configure Trusted Host in the Security menu had been incorrectly removed from the UI.
- 9013 – ALG – CDR logs – Enabling CDR logs did not warn the user that call disruption would occur when enabling this feature. The system now warns the user with the following message; **WARNING: All voice and video services will be interrupted. Do you want to continue?**
- 9093 – ESCVIU-95 – User Management – When User Management is enabled the ROUSER user account password was not able to be changed. The ROUSER account is now disabled when User Management is enabled.
- 9094 – ESCVIU-94 – H.323 – Clients list – Modified the system to allow a dynamically registering endpoint to be locked as a permanent client. This modification allows a dynamically registering endpoint to also unregister and then re-register from the Embedded gatekeeper with a locked client. The dynamically registering endpoint must re-register from the same IP and the same H.323 RAS ports. The Polycom

---

m100 client cannot be supported at this time because the source ports are assigned dynamically by the computer and may change when the m100 client is shut down and restarted.

- 9207 – ESCVIU-101 – Access Proxy – LDAP – VBP-E 2 Hop - In certain CMA deployments LDAP directory searches failed when deployed behind a remote location VBP-E Access Proxy configured to proxy to the headquarters VBP-ST. This issue is now resolved.
- 9215 – ESCVIU-100 – GUI – Internet Explorer version 8 and 9 when connecting to the system could take up to 2 minutes to receive a login. The issue is now corrected.
- 9262 – Stateful Failover – VBP-E – Port Forwarding – When creating a Port Forwarding rule on the VBP-E system with Stateful Failover enabled, the WAN Interface IP token HA\_VIP was not adding the correct rules to allow the port forwarding rule to function as designed.
- 9319 – ALG – H.323 – Modified all H.323 timers and enabled Stale Time by default. Field deployed systems with these values configured as non-default settings will not be modified, systems that are factory defaulted will use the new timer settings as defined below;

VBP-ST - Provider gatekeeper mode  
Modify Time-To-Live: Checked  
Time-To-Live (s): 30  
Delete stale clients: Checked  
Stale time (m): 1  
H.460.18 Support  
Keep-alive time (s): 30

VBP-E – WAN-side gatekeeper mode  
Delete stale clients: Checked  
Stale time (m): 1

VBP-E - Embedded gatekeeper mode  
Time-To-Live (s): 30  
Delete stale clients: Checked  
Stale time (m): 1

TLS Proxy – VBP-E Internal client - Forwarding gatekeeper mode  
Modify Time-To-Live: Checked  
Time-To-Live (s): 30  
Delete stale clients: Checked  
Stale time (m): 1

- 
- 9320 – WAN NAT – VBP-E – VBP-E system configured to support the WAN NAT feature deployed in a private DMZ received an ANNEX O inbound call as user@PUBLIC\_NAT\_IP. Certain gatekeepers require the ANNEX O message to be modified to only send the user portion. In previous VBP-E logic the system automatically removed the host portion if the IP matched the VBP-E's configured WAN IP address. With the system deployed in a NAT-ed environment the actual VBP-E WAN IP address no longer matched the incoming H.323 URI therefor the system forward this user@PUBLIC\_NAT\_IP address and call processing will fail if the gatekeeper cannot resolve this address.
  - 9349 – TLS Proxy – Internal Client – The recent race pacing feature modification performed in VOS 11.2.10 defined as issue 8622 created a client's list synchronization issue between the external and internal VBP's configured in TLS Proxy mode. TLS Proxy configurations must use the new H.323 timers discussed in issue 9319 to ensure the H.323 clients list remain synchronized.
  - 8884 – ALG – H.323 – VBP-ST – The H.323 ALG may restart when certain network delay conditions exist with Real Presence Mobile Android tablets.

---

## New Features introduced in VOS 11.2.10

- 8737 – ALG – H.323 WAN/LAN NAT – The system can now be installed behind a perimeter security NAT device. This allows incoming traffic to the public IP to be translated to the systems internal IP. This is typically called a private DMZ which allows devices in this DMZ to be configured with a private RFC1918 IPv4 address. The NAT configuration must be a Public IPv4 address configured for a one-to-one NAT translation without any port-mapping to the VBP-ST or VBP-E internal DMZ Subscriber/WAN IPv4 address.

---

Public NAT WAN IP address:

Private NAT LAN IP address:

---

- 8622 – ALG – H.323 – VBP-ST – Provider Gatekeeper performance enhancement - Rate pacing for keep-alive WAN traffic. The VBP-ST system will now rate-pace all keep-alive (or light-weight) RRQs sent from endpoints. The VBP-ST system will respond locally to this keep-alive traffic and will not forward this traffic to the Provider side gatekeeper.

The VBP-ST system will send a single keep-alive RRQ to the Provider gatekeeper at 50% of the gatekeeper TTL interval e.g. the default TTL for registration refresh interval is 300 seconds. The VBP will send a keep-alive at 50% of the TTL value or every 150 seconds. This reduces the keep-alive RRQ load on the Provider gatekeeper instead of forwarding one keep-alive RRQ for each endpoint registered to the VBP-ST.

When the endpoint sends an additive RRQ, a full RRQ, or a URQ, the VBP-ST will forward the message to the gatekeeper in order to keep the VBP-ST and gatekeeper client registration state in synch. The feature is only enabled on ST systems in Provider gatekeeper mode.

- 8199 – VoIP Traversal – TLS Proxy mode – The system can now be configured in TLS Proxy mode or TLS Routed mode depending on the solution requirements. TLS Proxy mode allows the system to proxy the application traffic as the configured VBP Public or Private interface IP's and removing the routed subnet requirement.
- 8067 – System – 6400LF2 – Removed all applications that allow a remote client to connect to the VBP that encrypt the session for transferring data to/from the remote network and to/from the core or headquarters network. This is a requirement for shipping VBP systems to Russia. A Russian part number must be order to have the system built with no encryption. Encrypted management session e.g. HTTPS, SSH are allowed to manage the system, these management applications will function as normal.
  - 8061 – GUI – 6400LF2 – The model name of this platform was changed to 6400LF2 and only if a disable encryption license key is applied. This was modified for homologation requirements.

## Fixes and Enhancements in VOS 11.2.10

- 8026 – ESCVIU-78 – H.323 – Calls to the default alias failed to route in certain origination scenario's
- 8387 – ALG - H.323 – DMA interoperability – DMA 4.0.1\_build\_4 version configured for a VBP-E for outbound dialing included a transportID field in the call setup message as the destination IP dialed by the user. This message type was not parsed or removed correctly by the origination VBP-E or the destination VBP-E
- 8565 – ALG – H.323 – DMA interoperability – When a VBP-ST registered endpoints unregisters from the VBP-ST configured for a DMA gatekeeper the VBP-ST send a URQ request to the gatekeeper to unregister the endpoints aliases. DMA now removes all known aliases for the VBP-ST Provider IP address and responds to the next keep-alive RRQ as “Full Registration Required”. This message indicates to the VBP-ST system that the gatekeepers registered clients list is no longer synchronized with the VBP-ST clients list. The VBP-ST now initiates an auto-registration cycle to re-synchronize the VBP-ST clients to the gatekeeper.

The VBP-ST will send an RRQ request to the gatekeeper one alias pair at a time and wait for a RCF response. During this process if a network delay condition exists, for example greater than 1 second delays and the VBP-ST is still receiving full RRQ's on the Subscriber interface to re-register. The VBP-ST will initiate multiple auto-registration process and eventually cause the ALG to exit. This condition is now resolved by not allowing the auto-registration process to execute more than one instance.

- 8630 – ALG - H.323 – DMA interoperability – The current DMA design allows calls to Inactive endpoints, when a VBP-ST registered endpoint calls this Inactive endpoints destination alias the DMA re-directs the call to this endpoint. If this endpoint is currently registered to another gatekeeper on the network the active gatekeeper will signal the endpoint to send a facility message “route call to gatekeeper” the VBP-ST ALG exits in this condition if the releaseComplete arrives before the setup message has been forwarded to the endpoints currently registered gatekeeper. This issue has only been observed if certain network conditions exist, this issue is now resolved.
- 8629 – ALG - H.323 – DMA interoperability – In certain gatekeeper RAS conditions “caller not registered” the VBP-ST incorrectly formatted the RRJ message and was not sent to the client.
- 8538 – ESCVIU-85 – Security – Certificate Store – The system would not allow the creation of a certificate with a hyphen included in the Common Name field. The system has been modified to support domain name characters per RFC952 - alphabet (A-Z) (a-z), digits (0-9), hyphen, period, and underscore
- 8636 – GUI - Web Server – Some web browsers send HTTP GET requests in multiple packets e.g. Chrome and some versions of IE. When using these web browsers the VBP web server processes this as two separate requests and resets the connection.
- 8657 – ESCVIU-84 - System – Kernel – 6400LF2 only - When the 11.2.x release was under development for the kernel port to linux 2.6.33, kernel logging was enabled and was left enabled when VBP VOS 11.2.3 was released. In certain conditions e.g. the system logging firewall messages created by the VBP's TCP connection limits 10/sec burst 20 caused a significant amount of traffic on the console port. This traffic caused the console driver to access and busy out all 4 CPU's in the quad core system. This resulted in the

---

systems inability for other applications to obtain CPU interrupts for processing and has the appearance of all services halting while this traffic condition exists. Kernel logging is now disabled on the 6400LF2 system.

- 8825 – ALG - H.323 – RTP port array – Noted below, the 9.1.5.x documented ports for all platforms were inadvertently changed to increase supported calls on the system. This change also modified the systems ALG RTP port array when 11.2.x was released to increase call capacity and was not documented correctly in the VBP configuration guide. This version modifies the ALG RTP array back to the documented values. This has no effect on the current system supported call values; this increased call modification made was for future scalability reasons.
  - 9.1.5.x releases
    - 16386 - 17286 (200EW,4300,4350,4350EW) (contiguous range)
    - 16386 - 25386 (5300-E/S10 and E/S25) (contiguous range)
    - 16386 - 34386 (6400-E and S85) (contiguous range)
  - 11.2.3 to 11.2.9
    - 16386 - 17286 (200EW,4300,4350,4350EW,4555) (contiguous range)
    - 16386 - 25386 (5300-E/S10 and E/S25) (contiguous range)
    - 16386 - 52386 (5300LF2-E/S10 and E/S25) (contiguous range)
    - 16386 - 52386 (6400-E and S85) (contiguous range)
  - 11.2.10
    - 16386 - 17286 (200EW,4300,4350,4350EW,4555) (contiguous range)
    - 16386 - 25386 (5300-E/S10 and E/S25) (contiguous range)
    - 16386 - 25386 (5300LF2-E/S10 and E/S25) (contiguous range)
    - 16386 - 34386 (6400-E and S85) (contiguous range)
- 1043 – ESCVIU-81 – H.323 – When adding static H.323 clients or locking a dynamic client in the list, the system did not save these changes which resulted in the client being deleted if the system was restarted.
- 8182 – H.323 – Whitelist/Blacklist – Modified the feature to allow new rule entries to not interrupt ongoing calls. If the administrator changes from Whitelist to Blacklist or Blacklist to Whitelist this action will be disruptive to ongoing calls.

Modified the feature for the VBP-ST to include RAS UDP 1719 to the block/allow rule set. Example: If the blacklist feature is enabled all remote H.323/H.460 clients will be able to register to the system. Adding a source IP to the blacklist will now add firewall rules to DROP RAS UDP 1719 from this source IP only. If the whitelist is enabled all remote H.323/H.460 RAS UDP 1719 client requests will be dropped and only the defined remote IP's will be allowed to register to the system.



- 8266 – GUI – H.323 – Activity, Call Status and VoIP ALG pages – minor wording changes

Previous GUI language;  
Current payload bandwidth:  
Estimated total bandwidth:

Changed to  
VoIP ALG Licensed Bandwidth In Use:  
Current Total Bandwidth With IP Overhead:

- 8259 – H.323 – DMA – VBP-ST interoperability with H.460 Subscriber side clients when the DMA is configured for an H.323 auto call model to select a routed or direct call. When calling from a Subscriber H.460 enabled endpoint to a Provider side endpoint the call was failing due to the direct call model with a H.460 endpoint.
  - 8322 – H.323 – DMA – VBP-ST interoperability with H.460 Subscriber side clients calling Provider side clients in a direct call model. The system was not translating the destCallSignalAddress correctly.
- 7788 – Security – Disabled SSLv1 and SSLv2 and removed weak ciphers from the system.
- 7816 – VoIP Traversal – LDAP – VoIP Traversal Authentication configured as LDAP would not accept an IP address entry.
- 7844 – ESCVIU-76 – Stateful Failover – Access Proxy failed to process requests after a reported 4hr time frame.
- 7916 – ESCVIU-77 – Firewall Logging – The Enabled Firewall Logging check box would not stay enabled after a submit.
- 7977 – VoIP traversal – A side effect of adding Vlan support for TLS in VOS version 11.2.6 – 7356 - would not allow the TLS Remote Client to use the default LAN interface for TLS traffic if Vlans were not enabled.
- 7749 - ESCVIU-75 – Access Proxy – Signed Certificates as the Subscriber Certificate – The system would use a signed certificate as the Subscriber Certificate but did not chain to the certificate authority (CA) correctly. Currently the system support 2 root CA certificates for certificate chaining, VeriSign and Go-Daddy. This modification allows the user uploaded VeriSign or Go-Daddy signed certificates to chain to the root VeriSign or Go-Daddy root CA preinstalled on the system. Currently the system does not allow the user to upload and use a different root CA.

## New Features introduced in VOS 11.2.6

- 7356 – VoIP Traversal - TLS Traversal remote client - VLAN capable and Access Proxy Added the ability to configure the LAN side of the Access Proxy to one VLAN, and the LAN side of the VoIP Traversal client to another VLAN. Reference the 11.2.6 VBP Configuration guide to configure the system.
- 6650 - ESCVIU-65 – H.323 – TCP keep-alive – In certain VBP deployments remote H.323 devices may be installed behind non VBP security appliances that monitor TCP connections for activity. In this scenario the security appliance may close the TCP connections between the far end VBP and the remote endpoint causing the call to drop. Setting the TCP keep-alive feature forces the endpoint to create a keep-alive packet on TCP connection's to the VBP for H.323 connections at the interval time set in the configuration file.
  - 7147 – EXT-4141 - Add a TCP keep-alive feature to H.323 page. Added a GUI option for TCP keep-alive for H.323 TCP connections. The minimum time is 120 (s)

---

### TCP Keep-Alive Time

Enables TCP keep-alive messages and sets the interval between messages in seconds. If this value is zero, no keep-alive messages are sent.

TCP Keep-Alive Time (s):

---

- Example /etc/config/alg\_defs.conf file

```
MGCP_CALLAGENT_IP=0.0.0.0
MGCP_CALLAGENT_PORT=2727
MGCP_MEDIAGATEWAY_PORT=2427
MGCP_NOTIFIEDENTITY_PORT=2432
SIP_CALLAGENT_IP=0.0.0.0
SIP_PORT=5060
GK_IP=12.48.260.19
SCCP_IP=0.0.0.0
TFTP_IP=0.0.0.0
SIP_SHARED_DIDS=off
MGCP_ASTERISK_PORT=6727
LAN_ALG_IP=192.168.1.1
ALG_VLAN=eth0
H323_GKMODE=3
H323_LANGK=
```

```
H323_GK_TTL=300
H323_MAX_ALIASES=0
H323_MOD_TTL=off
H323_TTL=300
H323_USE_MCAST=off
H323_STALEURQ=off
H323_STALEURQ_TIME=60
H323_NOTRAN_LCF=off
H323_DEF_ALIAS=7221
H323_DEF_ALIAS_TYPE=0
H323_NATTRAV=2
H323_NATTRAV_TIME=45
H323_PREVENT_UNREG=off
H323_LRQ_SIZE=off
H323_GK_ROUTED=off
H323_Q931_PORT=1720
OPTION=""
H323_TCP_KEEPALIVE_TIME=120
```

## Fixes and Enhancements in VOS 11.2.6

- Correction on VBP VOS 9.1.5.3 release note – License key – Support for 200Mbps of video on the 6400 platform only. The 200Mbps license key support is for the 6400LF2 platform only.
- VIDEO-93593 - HDX endpoints configured for dynamic management using the VBP-ST Access Proxy might not upgrade correctly under certain conditions when the HDX system is behind a remote NAT network environment. HDX software version 3.0.3 resolves this issue by supporting authenticated upgrades. HDX systems must first be manually updated to version 3.0.3. After the HDX is upgraded to version 3.0.3 future upgrades can be managed by the CMA server by the administrator.
- 5201 - ESCVIU-71 – 6400LF2 - VBP VOS 11.2.3 included a Linux kernel update from 2.4.24 to 2.6.33. 6400LF2 platforms have a storage device mounted by an internal USB controller, this device was randomly un-mounting itself and then re-mounting the USB attached storage device. The system could not re-mount the USB device successfully causing loss of GUI and SSH access to the system. After some period of time new H.323 registering systems and or H.323 calls will fail to be processed by the system. Updated the Linux USB device drivers to address this issue on 6400LF2 platforms only.
- 7002 – ESCVIU-68 – H.323 – This issue was a side affect from resolving bandwidth down speeding addressed in VOS version 11.2.3 - 5967 – ESCVIU-45. When LAN to LAN calls were placed and the system was in Embedded gatekeeper mode, the system sent a BRJ for the call with no currents calls being processed by the system. LAN to WAN calls were being process correctly, the issue only happen on LAN to LAN calls. This issue also affected WAN-side gatekeeper mode.
- 6528 – Security – Updated the SSH daemon to OpenSSH version 5.8p2
- 7521 – VIU-203 – License key – Display S or ST on the System page based on license key The system now displays S or ST based on H.460 license key.
- 6582 – ESCVIU-64 – Access Proxy - H.323 Needs the ability to enter FQDN within the CMA address field It is now possible to enter an FQDN in the server field for access proxy configuration. The access proxy will do an A lookup on the FQDN and use the resulting address with the configured port number to forward requests.
- 6934 - ESCVIU-70 – CMA 5.5 and VBP-E 9.1.5.3 dialing into Tandberg expressway hosting multiple domains does not work as the VBP is stripping the domain from the call setup.

This case is linked or duplicates of EXT-4046 and ESCVIU-67

Logic change: The user dialed string of user@host in any combination alias@IP or alias@domain sent from the endpoint in the ARQ to the Embedded Gatekeeper will be first resolved and then sent unmodified in the SETUP to the destination in the same field received in the ARQ. Since this field is sent by the endpoint (typically an h323-ID) the forwarded SETUP to the destination will also be the h323-ID.

---

When VBP's in the field are upgraded to this version and future versions, calls from VBP's with this version to older VBP versions is as follows.

Embedded Gatekeeper

VBP VOS 7.2.2 – will not receive user@host dialed strings unless an alias manipulation rule of @VBP\_WAN\_IP is configured.

VBP VOS 9.1.5.1 – Will receive user@host dialed strings

VBP VOS 9.1.5.3 – Will receive user@host dialed strings

VBP VOS 11.2.3 – Will receive user@host dialed strings

LAN Side Gatekeeper

VBP VOS 9.1.5.1 will strip the @VBP\_WAN\_IP\_or\_DNS before sending it to CMA – this logic has not changed

Calls from CMA with the unresolved string will be forwarded to the destination in the same field CMA sends the SETUP to VBP.

- 7084 – Access Proxy – VBP-E 2Hop – VBP-E Access Proxy with CMA when integrated with active directory using longer than expected user strings – Users were not able to login with active directory accounts, local accounts authenticated correctly – Dynamic mode provisioning message over 8190 bytes where not forwarded correctly - minor changes to buffering of provisioning messages over 8k was introduced.

## New Features introduced in VOS 11.2.3

- TLS VoIP Traversal – System – Added support for TLS Traversal as a new networking method for the VBP using a single UDP TLS port for traversal through the existing enterprise NAT/Firewall and a remote TLS VBP client for connecting remote branch office video systems to the core UC info-structure. This feature includes support for a legacy VBP-ST that is installed on the WAN/LAN (Subscriber/Provider) interfaces to connect remote branch office locations with a remote VBP-E TLS Traversal client.
- IPv6 – Network – Added support for IPv6 on the 4555, 5300LF2 and 6400LF2 platforms.
- HTTPS – Management – Added default HTTPS certificates for all platforms for management to the system.
- Certificate Store – System – Added the ability for the system to create CA, TLS Server, TLS Client, CSR and HTTPS certificates.
- User and Session Management – The system now support the ability to create non root user accounts. The system administrator can now create specific user accounts with administrator or auditor privileges. Administrators will have full access to the system, and auditors will only have privileges to view and clear and download audit logs.
- Audit Logging – System – Added support for the system to track configuration changes for any uses perform configuration changes to the system.
- 4999 – NAT – Added NAT support on a VBP-E system when configured in VRRP. The system will now accept the token name VRRP\_VIP as the Src IP field in the NAT statement. This token will only apply the NAT statement to the VRRP VIP IPv4 address for the WAN interface on the acting MASTER system.

## Fixes and Enhancements in VOS 11.2.3

- 6975 – Resolved a memory allocation issue in the Access Proxy process. A symptom of this issue could be seen as “Signing into Presence Server” on CMAD clients. If Access Proxy used all available memory, the process would restart and self recover in approx 15 seconds. Any CMAD client requesting Access Proxy services during this period would report the service as down and then re-authenticate. H.323 services would not be interrupted.
- 5967 – ESCVIU-45 – GUI – VBP now calculates the correct bandwidth usage when the H.323 device down speeds the bandwidth during the call from the initial requested call speed. This fix addresses the following configuration modes:
  - VBP-E Embedded Gatekeeper
  - VBP-E WAN side Gatekeeper
  - VBP-ST Provider Side Gatekeeper
- 6650 – ESCVIU-65 – H.323 – TCP keep-alive – In some installations the far end NAT router that is configured with or without a remote VBP may close the 1720 TCP port because of no activity and causing the call to drop. TCP keep-alive forces the remote client to send TCP keep-alive packets on port 1720. A new entry in the configuration file is needed to enable this support, a GUI option is not available at this time.
  - H323\_TCP\_KEEPA\_LIVE\_TIME=120 (value in seconds 120 or greater) to the etc/config/alg\_defs.conf file
- 6540 – ESCVIU-63 – Ethernet Drivers – During video calls with a bandwidth throughput of 30Mbps packet @ 4700-5000 packets per second or greater, occasional packet loss is experienced on RX side of the interfaces. This issue is only experienced on the 6400LF2 platform. Disabling NAPI within the driver resolved this issue.
- 4628 – ESCVIU-34 – Security – VBP 9.1.5.3 and prior version had a maximum 8 character GUI password length, with the new User and Session management feature the password length is 32 alpha, numeric, special characters supported.
- 5891 – ESCVIU-52 – GUI – Minor wording changes in the GUI
- 5233 – ESCVIU-43 – Firewall – Management Interface – The VBP-E system was incorrectly responding to management protocols on the LAN interface with the management interface configured if the radio buttons on the firewall page were unchecked. The workaround to this issue was to check the management protocols on the firewall page and LAN access to the system is now blocked and only traffic from the management subnet is allowed.
- 5670 – ESCVIU-44 - H.323 – WAN Side gatekeeper mode – Interoperability between a RadVision gatekeeper and a Tandberg endpoint with a VBP-E configured in WAN Side gatekeeper mode. The VBP-E was removing the clients alias list when the Tandberg endpoint sent a Keep-alive RRQ and the Radvision gatekeeper had not signaled support for keep-alive RRQ causing the Radvision gatekeeper to remove the endpoint from the registered clients list.

- 
- 5815 – ESCVIU-46 – H.323 – Embedded gatekeeper – This is related to issue 1463 - ESCVIU-27 – H.323 – Support for FACILITY – The Embedded gatekeeper now includes the destinationAddress in the redirected call SETUP
  - 6006 – ESCVIU-55 - Access Proxy – Enabling the Access Proxy and changing the admin password on 5300LF platforms only would cause the GUI to stop responding. This issue would not cause a service interruption.
  - 6126 – ESCVIU-58 – H.323 – H.460 – H.460.19 uses a RTP keep-alive payload type used for keeping the NAT router connection tracking entries alive, these RTP payload types should be dropped at the VBP-ST traversal server and not forwarded to the remote client. This issue is related to improving H.460 traversal with certain NAT routers as 5234. The system was not dropping these RTP payload types to the remote client and in some cases causing the remote client to reboot.



## New Features introduced in VOS 9.1.5.3

- 4699 - VIU-102 - Upgrade Firmware - Logging enhancement - The upgrade firmware page now displays more detailed error messages if an upgrade fails, e.g. Download Server DNS resolution failure, no route to host, connection refused, login failed, file permissions. Added download percentage display to the 5300, 5300LF, 6400, 6400LF, 6400LF2. The 200x, 4300, 4350x platforms already display the download percentage.
  - Upgrade error: Could not connect to download server, no route to host
  - Upgrade error: Could not connect to download server, connection refused
  - Upgrade error: Could not connect to download server, network is unreachable
  - Upgrade error: Could not connect to download server, connection timed out
  - Upgrade error: Could not log in to download server, credentials incorrect
  - Upgrade error: Could not find file on download server, check the file name
  - Upgrade error: Was not allowed to download file, check server permissions
  - Upgrade error: Failed to resolve Download Server DNS name. Verify the Download Server DNS name and the DNS settings on the network page are valid.
- 5279 - Disable Encryption - License Key - Added the ability to disable encryption based applications for shipping VBP platforms into countries that do not allow certain applications to be encrypted, e.g. PPTP, Site to Site VPN, Access Proxy. Encryption to the system for management is allowed and still enabled, e.g. HTTPS, SSH. When these applications are license key disabled the items are removed from the user interface.
- 5108 - Security – Whitelist/Blacklist - Added a user interface menu under VoIP ALG -- > H.323 -- > Whitelist/Blacklist. This feature allows the user to create IPv4 firewall rules to allow or deny specific source IP address or subnets from creating TCP port 1720 call SETUP connections to the VBP. This feature has been added to the VBP-E and VBP-ST platform, the feature will have more useful functionality on the VBP-E platform for allowing or blocking calls from remote H.323 systems. The feature is also enabled on the VBP-ST platform.
- 1463 – ESCVIU-27 – H.323 – Support for FACILITY messages – The VBP will now responds to FACILITY messages to redirect a call setup, i.e. routeCallToGatekeeper, routeCallToMC, and callForwarded. The system also translates the H.245 address for FACILITY messages with reason startH245.
  - 5297 - Alias Manipulation - When the VBP-E system is configured as LAN-side gatekeeper mode and the CMA is set to use this VBP-E system as its SBC/ALG. When a user dials an IPv4 address to the destination system the CMA inserts an @ character i.e. @1.1.1.1. The insertion of the @ symbol was introduced by the gatekeeper team to work around the issue described in Bug: 4765. With this issue resolved the gatekeeper team can now remove this dependency in future gatekeeper releases. With the new support for FACILITY messages as described in 1463 – ESCVIU-27 the below rules to remove the @ symbol from the redirected SETUP message is needed in certain cases for the destination system to route the call correctly.

When calling a system that supports FACILITY redirects, the VBP redirects the SETUP as destinationAddress - url-id: h323:@1.1.1.1 some systems won't route the call correctly to the destination with this string.

Adding the following Alias Manipulation rules to remove this symbol solves this issue in the FACILITY redirect scenario;

```
^@  
^h323:@
```

These rules will not be inserted on system upgrades, you will need to enter them manually. The rules will be present for new shipping systems or performing a factory default.

The help file on the Alias Manipulation page was update to include these new expressions.

- 4794 – EXT-2715 - TACACS support on the VBP-ST platform - TACACS is now enabled on the VBP-ST platform. TACACS authentication will be preformed on all management protocol to the system, if the remote TACACS server is unavailable the system will authenticate with the local system credentials.
- 4670 - ALG – H.323 – Alternate Q.931 port – Added the ability to change the Q.931 listening port of the system from the standard TCP port 1720 to a non-standard port. This feature was added to help work around SoHo NAT devices that either block this standard port, or manipulate the Layer 5 headers that can cause the call SETUP to fail. During this feature testing in proof of concept trials in the field it has proven to help solve CMA Desktop connectivity related issues. When setting this port it will change it for all users on the system. No modifications are needed on the H.323 client. The alternate Q.931 port will be assigned to the calling client in the ACF message when using a VBP-ST platform. This field is also present on the VBP-E platform. When changing the VBP-ST or VBP-E platforms to use a non-standard Q.931 port, the system will listen and respond to Q.931 setup requests on the GUI configured Q.931 port and the standard well known 1720 port.

When changing the Q.931 port on the VBP-ST platform to solve a remote CMA Desktop's connection issues behind a NAT router you may try a few well known ports e.g. 80, 110, 25, 21, 20. If you are planning to use port 80 for the Q.931 port, you must reassign the HTTP port for managing the VBP. If you have not reassigned the HTTP port on the Firewall page for management and assign port 80 as the Q.931 port and click Submit to save the changes the system will warn you;

**Error: Port 80 is currently used by the Web management GUI and cannot be used as the Q.931 port. You can remap the HTTP port on the [Firewall Page](#)**

When changing the Q.931 Port on either platform the active registered clients in the systems H.323 Clients List will be removed, you will need to wait for the clients to re-register before making test calls. If you are testing this feature on a VBP-ST platform with H.460 enabled the H.323/H.460 remote client will reregister to the system as half the period of the configured Keep-Alive Time (s) value. The default time of 45 (s) will cause the remote client to re-register in approx 22 (s). The H.323 clients list may not display the client for up to a minute even though the remote client reports that it is registered. If the remote client reports it is registered calls will now be possible using the new Q.931 port.

The default setting on a VBP-E system registered client can take up to 300 seconds or 5 minutes to re-register.

- 4996 – Access Proxy - Added Access Proxy client add and delete syslog messages without the need to enable any debug options on the system. This feature will be useful in diagnosing Access Proxy client issues when configuring the system for external syslog under the Services Configuration page setting Enable Remote System Logging. Local syslog files are limited to 2 x 32k files that wrap in a circular manner in the /var/log/ directory, messages and messages.old.
- 4995 – Access Proxy - Added Access Proxy start and stop syslog messages without the need to enable any debug options on the system. This feature will be useful in diagnosing Access Proxy issues when configuring the system for external syslog under the Services Configuration page setting Enable Remote System Logging. Local syslog files are limited to 2 x 32k files that wrap in a circular manner in the /var/log/ directory, messages and messages.old.
- 3880 – License Key – 200Mbps – Added the ability to support up to 200Mbps of video on the 6400LF2 platform only.

- 4227 – VIU-97 – GUI – Call Status – The VBP-E and VBP-ST systems now have a new GUI menu under Voip ALG -- > H.323 to view active calls, details about the call and the ability to disconnect the call.

## H.323 Call Status

[Help](#)


Current time: **Wed Jul 28 18:03:02 2010**

Current payload bandwidth: **256**

Estimated total bandwidth: **320**

The H.323 call status shows currently ongoing H.323 calls.

[Refresh Status](#)

H.323 Call Status		
Start-Time	Source	Destination
Jul 28 18:02:40	<b>8885</b> 192.168.1.50:5557	<b>5551000@12.48.270.1</b> <b>12.48.270.1:1720</b>
	Duration: 0:00:22 Bandwidth: 256 kbps Route Decision: AnnexO style alias Call-Status: H.245 signaling received and forwarded	
 <a href="#">Terminate Call</a>		


## Fixes and Enhancements in VOS 9.1.5.3

- 4596 – Access Proxy – Continuing to enhance the support for multiple clients that are installed behind SoHo or enterprise NAT devices. Issues have been found in the field in previous versions that cause the Access Proxy to not correctly track clients that are installed behind devices that can NAT a single client as multiple IPv4 addresses and may cause the client to display “Can’t connect to Presence server” Added syslog message for deleting client when iptables rules are not added.
  - 5530 – Modification made to the access proxies add client, delete client and the clients list clean up process which allows the mobile user to switch network interfaces immediately without experiencing re-authentication issues.
- 4599 – AccessProxy - Logging enhancement - Access Proxy now has a GUI item to enable debug messages for advanced troubleshooting.

The output of this debug will be only accessible from the CLI interface in the /var/log/ directory as accessproxy.log which is the active file, when this file reaches a 250K size it will be rotated to accessproxy.log.1. The logs will continue to rotate up to accessproxy.log.7 and then be rotated out and non recoverable. Depending on the log level selected and the amount of users trying to connect these logs can fill up and rotate within 1min.

Added basic Access Proxy message decode to syslog; this feature will provide some information to help solve connection related issues. By enabling Access Proxy syslog the system will send limited messages to the systems logging application; you can access these files on the CLI in the /var/log directory as messages and messages.old. Local syslog files are limited to 32k. If you wish to capture syslog on a remote syslog server configure the Remote Syslog Host and Enable Remote System Logging in the Service Configuration page on the GUI.

Added help text for new logging options.



**Settings**

Enable Access Proxy:

**Logging**

Enable Access Proxy syslog:

Enable Access Proxy debug:

Debug LogLevel:

- 5291- H.323 – Embedded Gatekeeper – VBP-E replies with LCF for an alias it does not know This was a side effect of feature request 4765. We now do not attempt to do a DNS lookup on an alias in an LRQ.
- 4409 – Network - DHCP WAN type – When the WAN type was set to DHCP and the network DHCP server replied with an Infinite IP address lease time the DHCP client daemon would exit. The DHCP client daemon was configured to restart if the application exited; this caused the system to continually restart. The DHCP client exiting behavior is correct when receiving an Infinite lease time, the system now will not attempt to restart if the network DHCP server sends an Infinite lease time.
- 5234 -H.323 - H.460.19 not working when NAT device in the path rewrites H.245 messages. Modified the H.460.19 logic to create symmetric RTP streams which avoids the NAT device rewriting the OLCAck port numbers. This issue can cause H.460 devices installed behind some NAT devices to receive RTP media “sometimes”. This intermittent issue was observed in endpoints behind Netgear NAT devices (WGR614v9 – firmware V1.2.2\_14.0.13NA) with no replication pattern.
- 4998 – Access Proxy - Firewall is required to be enabled before enabling the Access Proxy. The Access Proxy secures the application through firewall rules and therefore the firewall must be enabled. This issue was found in the field that some customers didn’t enable the firewall and remote clients could not log into the system. The Access Proxy will not start if the firewall is not enabled and will warn the user to enable the Firewall.
- 4283 – Route page - Removed the 20 route entry limitation. The new limitation is 75 entries.
- 4328 – ESCVIU-26 - Tandberg interoperability - Inbound calls with DST H323-ID sent with user@VBP\_WAN\_IP failed in LAN/Subscriber-side gatekeeper mode or Peering-Proxy mode. There is an existing work around by adding an Alias Manipulation rule to strip @VBP\_WAN\_IP. The system did parse this message correctly in Embedded Gatekeeper mode. The system previously only stripped the '@OUR\_WAN\_IP' part for the internal call routing logic. The system now removes this from the actual SETUP message as well before forwarding to the LAN side device.
- 4765 – H.323 – Embedded Gatekeeper mode - ARQ message handling – The VBP now attempts to resolve an FQDN even if no @ sign is present in the alias. This issue was present if the user dialed e.g. hd.polycom.com as a DNS name, the system attempted to look for a registered H.323-ID alias and then failed the call. The system now attempts to resolve the string as a H.323 alias, if no alias is found, attempt a SRV h323cs lookup, then A record lookup.
- 3918 – Access Proxy – Help file change - Committed new help text.
- 4309 – ESCVIU-24 – NAT – In previous VOS versions it was possible to enter duplicate entries. The system now verifies the protocol, source port, and WAN IP when checking for duplicate entries. If these 3 fields match an existing entry, the new entry is not added and the following warning message is displayed
  - **The source already exists.**
- 4718 - GUI - User Commands page - Edgewater KB reference – Modified Help page language.

- 
- 4745 - GUI - SIP page - Help file - language change - remove or replaced references to EdgeMarc and EdgeProtect with VBP-E and VBP-ST.
  - 4955 - DHCP Server – Disabled the DHCP server on VBP-ST platforms. The DHCP server is now always disabled on VBP-ST platforms.
  - 4937 – ESCVIU-40 -H323 - Codian MCU dialing IP only – When configuring the VBP-E system with a default alias the inbound call did not route correctly. When the Codian MCU dialed the VBP with a IP only the Codian would configure a destination alias as a transported with the WAN IP of the dialed VBP IP address. The VBP default alias logic saw this as a valid alias and did not route the call correctly. A work around is available by dialing user@VBP\_WAN\_IP. The VBP now checks whether it understands the destinationAddresses passed in the Setup, If it does understand them, it leaves them alone, otherwise it removes them and adds a default alias.
  - 4418 – ESCVIU-29 - NAT page - Wording change Fixed – The wording read “For static NAT to function, WAN NAT must be enabled” the changed language is now “For static NAT to function, LAN NAT must be enabled
  - 4718 - GUI - User Commands page - Edgewater KB reference.
  - 4775 – Access Proxy – Removed a system call which caused the Access Proxy not to start after factory default. This issue was only present in an intermediate Polycom hot fix, version 9.1.5.1 did not have this issue.
  - 4679 - H.323 – call looping caused the ALG to exit – In certain calling cases when the called endpoints SETUP message is looped back to the same VBP-ST the ALG will exit and restart. This exit was due to a second H.225 connection being received with the same Call-ID as the previous call. We now detect and prevent these loops. An example of this is; when a call is received on a CMA Desktop client from the system and the call completes and the call ends, the receiving client now selects the recent call history and redials the previous call, the CMA Desktop client stores the VBP-ST IP address that its registered to as the last received call. When the user dials this IP address the CMA server can route this call to a VBP-E system that provides off net dialing for the enterprise. The VBP-E system now routes this call back to the VBP-ST and creates a call loop.

## New Features introduced in VOS 9.1.5.2

- 200E hardware platform introduced in VOS 9.1.5.2

## Fixes and Enhancements in VOS 9.1.5.2

- 3546 - Added 200E hardware ID support
- 4213 - VIU-94 - Access Proxy - NTLM string longer than 512 is not being forwarded: Increased buffer size to 2048 to handle longer NTLM authorization messages. This issue was found after the production release of 9.1.5.1, some Windows system platforms received service updates to their NTLM libraries which caused the NTLM authorization string to be longer than 512.
- 4314 – ESCVIU-25 – Gatekeeper neighboring in LAN/Subscriber-side gatekeeper mode with a CMA gatekeeper – When gatekeeper neighboring to a providers network for ISDN offnet dialing, the providers gatekeeper was re-writing the destination alias in the LCF, when the call SETUP arrived with this modified alias the VBP's ALG did not track the original LRQ and modified LCF correctly resulting in a ALG restart. Bug 4320 was also addressed as a direct cause on Bug 4314 – an incorrect source port was assigned as port 0 for transparent LCF responses.
- 3598 – SIP – The system by default is configured with a SIP Server of 0.0.0.0, after an unknown time period the ALG will restart.
- 4690 – Access Proxy – Change the default session timer to 30 mins from 60 mins. This timer is used to clean up Access Proxt clients that have disconnected from the system without logging out.
- 4689 – VIU-101 – Access Proxy – Authorizations for clients using Network credentials or cached network credentials could not login. The Access Proxy was not updating the content length of the authorization fields be forwarded to CMA. The CMA server was rejecting the authorization as a bad request.
- 4599 – Access Proxy – Logging cleanup
- 4596 – Access Proxy – Supporting multiple clients behind a SoHo NAT device was not functioning correctly. The client tracking logic only allowed for 1 device behind a SoHo NAT, when this device logged out the remaining clients experienced a loss of Presence and LDAP directory services.
- 4600 – Access Proxy – Configuration file cleanup.



- 
- 2874 – Access Proxy – Access Proxy configuration files not saved with the “ewn save” command – accessproxies.conf and accessproxy.conf now saved correctly.
  - 2961 – Access Proxy – Access Proxy UI configuration allowed a duplicate “Subscriber port” to be configured.

## New Features introduced in VOS 9.1.5.1

- None

## Fixes and Enhancements in VOS 9.1.5.1

- 4074: Log rotation fix for iptables logging - log rotation capability has also been added to Access Proxy, the system will now have 8, 250K ap-iptables.log files located in /var/log that track the dynamic “add” or “delete” firewall rules for authenticated VC2 based endpoints. This file also tracks VC2 endpoints that have become unavailable that indicates they have been “deleted”.
  - ap-iptables.log
  - ap-iptables.log.1
  - ap-iptables.log.2
  - ap-iptables.log.3
  - ap-iptables.log.4
  - ap-iptables.log.5
  - ap-iptables.log.5
  - ap-iptables.log.6
  - ap-iptables.log.7
- 4075: Fixed accessproxyc startup problem with multi cores, 6400, 6400LF, 6400LF2

## New Features introduced in VOS 9.1.5

- Copied key/cert to /usr/local/ssl/certs
- Access Proxy
  - Added support for HDX. Changed handling of the incoming authentication message from the HDX client.
- Allow LAN side E/P's to dial ANNEX O If an incoming call used an AnnexO dialing string where the IP address was the address of the system itself, we would not forward the call. Now we strip of the IP address from the alias if it is matching the address of the system itself, and completes the call using the alias part of the AnnexO string.

---

## Fixes and Enhancements in VOS 9.1.5

- 2298 - Annex-O LAN->LAN calls are GK routed.
- 3883 - VBP incorrectly assigning RTP ports We now attempt to match the RTP forwarding entries according to the signaled session IDs so that the forward and reverse stream gets the same port number.
- 3857 - Access Proxy - Enable Logging. Default Access Proxy.conf file has been copied to /etc/default/ for reference. Additional enhancements to the log messages to provide before information.
- 3858 - Access Proxy - Added Log Level support. Access proxy can now print out logs of varying levels by modifying /etc/config/Access Proxy.conf. Update LOG\_LEVEL with either LVL\_INF, LVL\_DBG, LVL\_DAT.
- 3867 - Access Proxy - HTTPS access to the system on alternate port. Firewall rules in config\_ep\_fw.sh and config\_em\_fw.sh have been updated. Text/Warnings has also been updated on the Firewall page, HTTPS Certificate page and the Access Proxy page.
- 3873 - Access Proxy - VRRP Support. Access proxy will start via /etc/Access Proxyrc if VRRP is enabled and is in MASTER state. Access Proxy will self-terminate if the state changes to BACKUP.
- 3873 - Access Proxy - VRRP Support. Modified config\_vrrp.sh to insert the appropriate allow iptables rules when the system is running in VBP-ST mode.
- 3859 - In Embedded Gatekeeper mode, not all the aliases are display this limitation has been removed.
- Message of the Day" configured or not; a longer than 8 characters password will now be rejected.
- 3929 - bandwidth tracking problem for h.460 nat'd endpoint initiated calls, this is a result of the fix for bug 2217 and is now resolved.

## New Features introduced in VOS 9.1.4

- Access Proxy Secure ALG functionality: In secure mode, the Access Proxy will have the following functionality:
  - Automatic AdapterProbe message response.
  - Automatic UpdateCheck message response with xml: <appUpdate>NONE</appUpdate>
  - Default iptables rule for blocking ALL traffic to XMPP (5222) and LDAP (389) ports.
  - Authentication message validation.
  - Dynamic addition / deletion of iptables access rule per user based on authentication 200OK response from CMA Server.
  - Addition of internal client list for tracking client access.
  - Log out handling → removes client from internal ap-client.list, iptables access rule removal.
  - Heartbeat handling → updates the session time for client in internal list.
  - Session time expiration handling (60 minutes) → Removes expired clients from the list and iptables.
  - Access Proxy now runs in Secure mode as a default.
  - Debug log rotation capability has also been added to Access Proxy, the system will now have 8, 250K accessproxy.log files located in /var/log note: debug is NOT enabled by default and must be enabled in the /etc/config/accessproxy.conf file please contact Polycom technical services for the correct instructions
    - accessproxy.log
    - accessproxy.log.1
    - accessproxy.log.2
    - accessproxy.log.3
    - accessproxy.log.4
    - accessproxy.log.5
    - accessproxy.log.6
    - accessproxy.log.7
- Bug 4383 Added the option "Supports Additive RRQ" in the RCF response from our embedded GK. This should allow our downstream VBP-ST to register more than 25 endpoints.

## Fixes and Enhancements in VOS 9.1.4

- 3483 - Added the option "Supports Additive RRQ" in the RCF response from our embedded GK. This should allow our downstream VBP-ST to register more than 25 endpoints.
- 3053 - Inconsistent GUI password login length when you have "HTTP Short System Message" The behavior is now the same whether there is a "Short System Authorization

- 2542 - "?" is not allowed as the first character in the password. It is now possible to use "?" in GUI passwords, as the first character or any other character.

### **New Features introduced in VOS 9.1.3**

- Access Proxy functionality was added to the VBP-ST system which can be accessed through the menu. In addition, you will also see the "Access Proxy" configuration on the VBP-E series appliances, the feature is not fully supported on the E series system in this version, please do not attempt to configure this feature in this version. The E series Access Proxy feature will be supported in a future Polycom VBP VOS version.
- Security update: Upgrading openssh-4.0p1 to openssh-5.1p1

### **Fixes and Enhancements in VOS 9.1.3**

- Enhancement: Polycom private / public security keys were added to ST and E models.
- 3426 - When HTTPS management is enabled, an attempt to add an HTTPS proxy server will now result in a message instructing the user to disable the HTTPS management from the Firewall page. If after the addition of the HTTPS proxy server, the HTTPS management is enabled, a message stating that HTTPS proxy and HTTPS management will be using different ports will be displayed.
- 3293 - NAT GUI: leading and/or trailing spaces in the port fields cause SNAT rule to not be applied in iptables. Leading and trailing spaces in the port fields caused parsing problems in the scripts. When saving the NAT rule, spaces are now stripped out of the rule before it is saved.
- 3257 - Re-enable MPPE support in kernel for PPTP server.

### **New Features introduced in VOS 8.11.1**

- 6400LF2 platform was introduced in VOS 8.11.1

### **Fixes and Enhancements in VOS 8.11.1**

- 0899: "Erase" button did not function on 5300LF. The button now works the same as on all the other devices which is as follows:
  - Pressed once: Nothing happens.
  - Pressed twice: The CLI password is reset.
  - Pressed three times: The device is set to the factory defaults
- 3191 - Default gateway was not being set on the subscriber eth0 interface of "ST" devices.
- 2929 - Removed Test UA from GUI.
- 3546 - VBP system reports a 200AW hardware type but actual hardware is a 200EW, the issue is now resolved.
- 3012 - ALG crashes with a LifeSize Express endpoint places call, the issue is now resolved.

---

## New Features introduce in VOS 8.9.1

- Support for VBP 200EW and VBP 4350W was added.
- DHCP options 67 (boot file), 150, 151, 159, & 160 were added to DHCP GUI page for better interoperability with Polycom phones.
- H.323 activity log is now written to a separate log file with a maximum of 25 entries and with newer entries on top of the file. This prevents the H.323 activity log from being overwritten by other syslog activity.
- Added more feedback and controls to the upgrade page. Added a checkbox that displays the output from the upgrade command. Added the platform name to the upgrade page. Added a checkbox to enable/disable the FTP server ping check. Improved error feedback when an upgrade fails.
- Message of the Day (MOTD) is now displayed on VBP-ST systems.
- Feature/Bugfix: Improved reliability of VRRP. Numerous fixes: + Re-applied patches for multiple race-conditions. + Modified VRRP to only advertise on LAN link. WAN link status is still monitored but only the LAN has advertisements. This should prevent ping-ponging of state due to conflicting advertisements on different links. + Re-enabled revertive mode and made it user configurable. + Modified keepalived's script notification to be synchronous to fix a state issue race condition + Added VRRP state check in ALG causing ALG to self-terminate if we're in backup mode to prevent a situation where ALG is running even though we're in backup mode. + Increased default advertisement interval to 3 seconds to prevent VRRP state from going from FAULT to BACKUP to MASTER when recovering from a fault.

## Fixes and Enhancements in VOS 8.9.1

- Enhancement: Capability was added to function in a router only mode.
- 2832 - Ppoe was not coming up on WAN after the execution of "ewm load" command. This problem is now fixed.
- 2558 - Multicast gatekeeper requests were not being answered by VBP. This problem is now fixed.
- 2733 - LAN to LAN call using prefix routing was failing. This problem is now fixed.
- 2560 - VBP was not forwarding LRQ on the WAN side. This problem is now fixed.
- Bug fix: ALG was failing if a call came on a shared call appearance phone. This problem is now fixed.
- 2806 - All references to V2IU were converted to VBP in 200 and 4350 series.
- 2810 - SIP UA and GW were removed from 200 series GUI. Test UA, however, has not been removed since no analog ports are needed to run Test UA.
- 2808 - (200 Platform) A video call would terminate by itself after a certain amount of time.
- 2582 - One way audio was observed on certain H.460 endpoints. This problem is now fixed.
- 2267 - Q.931 was not being blocked when H.323 was enabled. TCP port 1720 is now blocked by firewall when H.323 is enabled which blocks Q.931 traffic.

- 
- Bug - H.323 - Transparent LRQ in LAN GK mode was not working.
  - Bug - ALG was failing while receiving an incoming WAN call in LAN side gatekeeper mode. This problem is now fixed.
  - 1288 - H.460.18 traversal was not working when used with a RadVision GK and a Tandberg endpoint.
  - Bug - ALG was failing when endpoints were registering with multiple aliases containing the same string.
  - Bug - SIP stale RTP deletion feature was incorrectly deleting active H.323 calls which would cause ALG to malfunction.
  - 2217 - LAN side prefix routing is counting bandwidth, the issue is now resolved.
  - 2496 - Removed the Route GUI page and renamed the VoIP subnet routing page to Route. VoIP subnet routes are not limited to the ALG so the two pages were redundant.
  - 140 - ADSL-PPPoE is displayed in the GUI for the following platforms 5300, 5300LF, 6400, 6400LF, 6400LF2, this is not a support WAN type for these platforms. Removed ADSL-PPPoE network option from the 5300, 5300LF, 6400, 6400LF, and 6400LF2.
  - 1848 - 6400 and 6400LF does not have HTTPS as an option in the GUI. Added support for HTTPS on 6400, 6400LF. Added of the certificate link and the HTTPS firewall check box for these platforms.

## Upgrade Instructions

This version of software is available on the Polycom Support FTP site: <ftp.support.polycom.com>

It is recommended you reboot the Polycom VBP Series appliance prior to doing the upgrade. This will ensure there is enough dynamic memory available to handle the upgrade process.

When you update your software all services will be unavailable for several minutes. It is therefore advised that upgrades be performed during a maintenance window when VoIP traffic can be interrupted.

## Upgrade procedure

- 1) Use a web browser to connect to the **VBP** appliance.
- 2) Click on the **Upgrade firmware** link. Use the page defaults.
- 3) Press **Submit**.
- 4) Follow the progress of the upgrade using the "refresh the upgrade status" link.
- 5) When the Write process begins, please heed the warning:

**WARNING!!! Do not change the configuration or power off the device until the write is 100 percent complete. The device may become unusable if the write is interrupted.**

- 6) The system will automatically restart after the new image has been loaded. After the upgrade process has completed, check that the new version number is displayed on the main System page.

## Obtaining Further Assistance

Please contact the Polycom Technical Services for assistance.