

# Polycom® UC Software 5.9.1

## Applies to Polycom® VVX® Business Media Phones, Polycom® VVX® Business IP Phones, and Polycom® SoundStructure® VoIP Interface Phones

Polycom announces the release of Polycom® Unified Communications (UC) Software, version 5.9.1. This document provides the latest information about this release.

### Contents

<b>What's New</b> .....	<b>2</b>
<b>Install</b> .....	<b>4</b>
<b>Version History</b> .....	<b>7</b>
<b>Language Support</b> .....	<b>11</b>
<b>Security Updates</b> .....	<b>12</b>
<b>Resolved Issues</b> .....	<b>12</b>
<b>Known Issues</b> .....	<b>12</b>
<b>Updates to Previous Software Releases</b> .....	<b>14</b>
<b>Get Help</b> .....	<b>36</b>
<b>Copyright and Trademark Information</b> .....	<b>37</b>

## What's New

Polycom Unified Communications (UC) Software 5.9.1 is a release for Open SIP and Skype for Business deployments. These release notes provide important information on software updates, phone features, and known issues.

### ***Future Feature Releases for VVX Business Media Phones***

Customers in Skype for Business deployments should only use software releases that have been qualified by Microsoft or the maintenance releases built on a qualified release.

Microsoft qualification dates might be behind Polycom latest UC Software release dates. Customers are requested to check for all Microsoft qualified releases at [Polycom Support Site](#) before deploying new software.

### ***UC Software 5.9.1 Support***

Polycom UC Software 5.9.1 supports the following Polycom endpoints.



Support for Lync 2010 is limited to testing of basic call scenarios. Microsoft support of Lync and Skype for Business is documented on Microsoft's website. Microsoft does not currently support IP phones on Lync 2010. For information, see IP Phones on Microsoft Support.

#### **Supported Phones**

<b>Phone Model</b>	<b>Skype for Business On-Premises</b>	<b>Skype for Business Online</b>	<b>Open SIP</b>
VVX 101 business media phone	No	No	Yes
VVX 201 business media phone	Yes	Yes	Yes
VVX 300/301/310/311 business media phones	Yes	Yes	Yes
VVX 400/401/410/411 business media phones	Yes	Yes	Yes
VVX 500/501 business media phones	Yes	Yes	Yes
VVX 600/601 business media phones	Yes	Yes	Yes
VVX 1500 business media phone	No	No	Yes
VVX 150 business IP phone	No	No	Yes
VVX 250 business IP phone	Yes	No	Yes
VVX 350 business IP phone	Yes	No	Yes
VVX 450 business IP phone	Yes	No	Yes

VVX D60 Wireless Handset and Base Station	No	No	Yes
SoundStructure VoIP Interface Phone	Yes	Yes	Yes

Polycom UC Software 5.9.1 supports the following Polycom accessories.

#### Accessory Support

Accessories	Skype for Business	Open SIP
Polycom® VVX® Camera	No	Yes
Polycom® VVX® Color Expansion Module	Yes	Yes
Polycom® VVX® Expansion Module	No	Yes
Polycom® EagleEye™ Mini Camera	Yes	Yes
Polycom® VVX® EM 50 Expansion Module	Yes	Yes

Polycom UC Software 5.9.1 includes the following enhancements:

- [Enhancement to VLAN ID](#)
- [Wi-Fi Dongle Support](#)

## Enhancement to VLAN ID

After installing a new software package on VVX phones and changing the Virtual Local Area Networks (VLANs), the following are behavioral changes in VVX phones:

### Updater

The phone doesn't reboot and starts the DHCP sequence on new VLAN to get the new IP address.

### Application

- The phone doesn't restart and triggers the DHCP sequence on discovering a valid VLAN ID from an invalid VLAN ID to get the new IP address.
- Phone restarts and triggers the DHCP sequence on discovering any VLAN ID from an invalid VLAN ID to get the new IP address.

## Wi-Fi Dongle Support

Polycom VVX phones now support Edimax USB Wi-Fi Dongle (EW-7811UTC) along with the Polycom Wi-Fi wireless network adapter.

## Configuration File Enhancements

The following table lists configuration file enhancements that include new or changed parameters for the Polycom UC Software 5.9.1 release. For more information on using configuration parameters to enable or disable features, see the latest *Polycom UC Software Administrator Guide* for your release, available on [Latest Polycom UC Software Release](#).

### Configuration File Enhancements for UC Software 5.9.1

Template	Parameter	Permitted Values	Change Causes Restart or Reboot
video.cfg	video.profile.H264.packetizationMode0.payloadType	Specifies the RTP payload format type for H264/90000 packetization Mode 0 MIME type. 109 (default) 96 to 127	Yes
video.cfg	video.profile.H264.payloadType	Specifies the RTP payload format type for H264/90000 Mode 1 MIME type. 99 (default) 96 to 127	Yes

## Install

Consider the following information when installing or updating to Polycom UC Software 5.9.1:

- You must use BToE 3.8.0 or later with UC Software 5.9.1. Polycom recommends you upgrade existing BToE and PDC desktop applications to the latest version starting with Polycom UC Software 5.9.1. If you update the BToE or PDC application without updating to UC Software 5.9.1 or vice versa, the applications don't work with Polycom phone.

For more information, see [Updating to the Latest Versions of the Polycom Better Together over Ethernet \(BToE\) and Polycom Desktop Connector \(PDC\) Desktop Applications \(EA 318\)](#)

- Before updating your VVX 1500 phone to UC Software 5.9.1, make sure you first update the phone to BootBlock 3.0.4.

For more information see [Technical Bulletin 695: Upgrading the Polycom VVX 1500 Business Media Phone to UC Software 5.2.0](#).

## Download the Distribution Files

To download UC Software 5.9.1, you can choose the combined UC Software package or the split UC Software package, both in ZIP file format. The combined version contains all files for all phone models. The split software package is smaller, downloads more quickly, and contains sip.ld files for each phone

model, enabling you to choose provisioning software for your phone model and maintain software versions for each model in the same root directory.

For general use, Polycom recommends using the split resource file that corresponds to the phone models for your deployment. To match the correct UC software resource file to your phone model, see the table [Understand the Combined ZIP and Split ZIP Files](#). If you are provisioning your phones centrally using configuration files, download the corresponding resource file and extract the configuration files to the provisioning server, maintaining the folder hierarchy in the ZIP file.

The current build ID for the sip.ld and resource files is **UCS 5.9.1.0615 rts10**.

## ***Understand the Combined and Split ZIP Files***

To understand the files distributed in the combined ZIP file, refer to the following table.

<b>Distributed Files</b>	<b>File Purpose and Application</b>	<b>Combined</b>	<b>Split</b>
3111-40250-001.sip.ld	SIP application executable for VVX 101	x	✓
3111-40450-001.sip.ld	SIP application executable for VVX 201	x	✓
3111-46135-002.sip.ld	SIP application executable for VVX 300	x	✓
3111-48300-001.sip.ld	SIP application executable for VVX 301	x	✓
3111-46161-001.sip.ld	SIP application executable for VVX 310	x	✓
3111-48350-001.sip.ld	SIP application executable for VVX 311	x	✓
3111-46157-002.sip.ld	SIP application executable for VVX 400	x	✓
3111-48400-001.sip.ld	SIP application executable for VVX 401	x	✓
3111-46162-001.sip.ld	SIP application executable for VVX 410	x	✓
3111-48450-001.sip.ld	SIP application executable for VVX 411	x	✓
3111-44500-001.sip.ld	SIP application executable for VVX 500	x	✓
3111-48500-001.sip	SIP application executable for VVX 501	x	✓
3111-44600-001.sip.ld	SIP application executable for VVX 600	x	✓
3111-48600-001.sip	SIP application executable for VVX 601	x	✓
2345-17960-001.sip.ld	SIP application executable for VVX 1500	x	✓
3111-48810-001.sip.ld	SIP application executable for VVX 150	x	✓
3111-48820-001.sip.ld	SIP application executable for VVX 250	x	✓
3111-48830-001.sip.ld	SIP application executable for VVX 350	x	✓
3111-48840-001.sip.ld	SIP application executable for VVX 450	x	✓
3111-33215-001.sip.ld	SIP application executable for SoundStructure VoIP Interface.	x	✓
3111-17823-001.dect.ld	SIP application executable for VVX D60 Wireless Handset and Base Station.	x	✓
sip.ld	Concatenated SIP application executable.	✓	X

Distributed Files	File Purpose and Application	Combined	Split
dect.ver	Text file detailing build-identification(s) for the VVX D60.	✓	✓
sip.ver	Text file detailing build-identification(s) for the release.	✓	✓
000000000000.cfg	Master configuration template file.	✓	✓
000000000000-director y~.xml	Local contact directory template file. To apply for each phone, replace the (zeroes) with the MAC address of  the phone and remove the ~ (tilde) from the file name.	✓	✓
applications.cfg	Configuration parameters for microbrowser and browser applications.	✓	✓
device.cfg	Configuration parameters for basic device configuration.	✓	✓
features.cfg	Configuration parameters for telephony features.	✓	✓
firewall-nat.cfg	Contains configuration parameters for telephony features.	✓	✓
H323.cfg	Configuration parameters for the H.323 signaling protocol.	✓	✓
lync.cfg	Contains Lync specific configuration parameters.	✓	✓
pstn.cfg	Contains parameters for PSTN use.	✓	✓
reg-advanced.cfg	Contains configuration parameters for the line and call registration and advanced phone feature settings.	✓	✓
reg-basic.cfg	Configuration parameters for line and call registration and basic phone settings.	✓	✓
region.cfg	Configuration parameters for regional and localization settings such as time and date and language.	✓	✓
sip-basic.cfg	Configuration parameters for the VoIP server and softswitch registration.	✓	✓
sip-interop.cfg	Configuration parameters for the VoIP server, softswitch registration, and interoperability configuration.	✓	✓
site.cfg	Configuration parameters that are set for each site.	✓	✓
video.cfg	Configuration parameters for video connectivity.	✓	✓
video-integration.cfg	Configuration parameters for SoundStation IP 7000 and Polycom HDX system integration.	✓	✓
Welcome.wav	Startup welcome sound effect.	✓	✓
LoudRing.wav	Sample loud ringer sound effect.	✓	✓

Distributed Files	File Purpose and Application	Combined	Split
Polycom-hold.wav	Sample ringer sound effect.	✓	✓
Warble.wav	Sample ringer sound effect.	✓	✓
polycomConfig.xsd	Master configuration file that contains the parameters and its values.	✓	✓

## Version History

This following table lists the release history of Polycom Unified Communications (UC) Software.

### Version History

Release	Release Date	Features
5.9.1	January 2019	This release includes enhancement to VLAN ID and Wi-Fi dongle support.
5.9.0	December 2018	This release includes important field fixes and support for following features: <ul style="list-style-type: none"> <li>• Session Traversal Utilities for NAT (STUN)</li> <li>• Device Analytics Support for PDMS-SP</li> <li>• Multilevel Precedence and Preemption (MLPP) for Assured Services - Session Initiation Protocol (AS-SIP)</li> <li>• Support for H.264 Packetization Mode</li> <li>• Enhanced Busy Lamp Field (BLF)</li> <li>• Busy Lamp Field Hold Alerting</li> <li>• Busy Lamp Field (BLF) Spontaneous Call Appearance on Per BLF Basis</li> <li>• Enhanced Feature Key Macro Actions</li> <li>• Retrieve Logs from Support Information Package Page in the Web Configuration Utility</li> <li>• Simple Certificate Enrollment Protocol</li> <li>• Privacy for Call Logs and Contacts</li> <li>• Enhancement to Wireless Network Connectivity</li> <li>• Call Hold Timer</li> <li>• GZIP Encoding of SIP INFO Messages</li> <li>• Enhanced Boss-Admin for VVX Phones</li> <li>• Web Sign In for Skype for Business On-Premise Deployment</li> </ul>
5.8.2	November 2018	This release includes important field fixes.
5.7.4	November 2018	This release includes important field fixes.
5.6.4	October 2018	This release includes important field fixes.

<i>Release</i>	<i>Release Date</i>	<i>Features</i>
5.8.1	September 2018	This release includes important field fixes and support for following features: <ul style="list-style-type: none"> <li>• Polycom EagleEye Mini Camera Support</li> <li>• Forward Error Correction</li> <li>• Simulcast Video</li> <li>• Centralized Conference Control Protocol (CCCP) Conference View Support</li> <li>• Quality of Service (QoS) for Skype for Business Video Calls</li> <li>• Toggling Between Audio-only or Audio-Video Calls</li> </ul>
5.7.3	September 2018	This release includes important field fixes.
5.6.3	June 2018	This release includes important field fixes and enhancement to include the following new directives to upload and download the certificate and CSV files: <ul style="list-style-type: none"> <li>• CERTIFICATE_DIRECTORY</li> <li>• FLK_DIRECTORY</li> </ul>
5.8.0	June 2018	This release includes support for the following features: <ul style="list-style-type: none"> <li>• Introducing Polycom VVX Business IP Phones</li> <li>• Open SIP Enhancements <ul style="list-style-type: none"> <li>➢ Enhanced IPv4 ICMP Management</li> <li>➢ Wireless Network Connectivity</li> <li>➢ Support for REST API</li> <li>➢ Uploading Logs to a USB Flash Drive</li> <li>➢ uaCSTA Lines</li> <li>➢ Enhancements to Check Sync Event</li> <li>➢ Early Media Call Handling Support</li> <li>➢ Voice Quality Monitoring Support for the OPUS Codec</li> <li>➢ BroadSoft Aggregated Self-Presence</li> </ul> </li> <li>• Skype for Business Enhancements <ul style="list-style-type: none"> <li>➢ Hybrid Line Registration</li> <li>➢ Support for PSTN Gateway on Failover</li> <li>➢ Reverse Name Lookup</li> </ul> </li> </ul>
5.7.2	May 2018	This release includes important field fixes.
5.6.2	April 2018	This release includes important field fixes.
5.7.1	March 2018	This release includes important field fixes and enhancement for Direct Inward Dialing number on VVX business media phones.
5.5.4	January 2018	This release includes important field fixes.



<i>Release</i>	<i>Release Date</i>	<i>Features</i>
5.7.0	December 2017	<p>This release includes support for the following features:</p> <p><b>Open SIP Enhancements</b></p> <p>This release introduced support for BroadSoft User Interface theme, Executive-Assistant Enhancements, Custom BroadSoft Executive-Assistant Enhanced Feature Keys, Client-Side Sorting for Open LDAP servers, Securely Store LDAP Credentials on VVX phones, Voice over Secure IP, Hide the MAC Address, Enhanced E.911, DNS Cache Override, Assured Services - Session Initiation Protocol (AS-SIP), Custom URL Location for Installing LDAP server certificates, Emergency Instant Messages - GENBAND, Default Off-Hook Phone screen, Enhanced Feature Keys Enhancements, Bluetooth Support for VVX Business Media Phones, Reset Phone without Admin Password, Prevent Call Park on Busy Orbits, View Phone Memory Usage Alert.</p> <p><b>Skype for Business Enhancements</b></p> <p>This release introduced support for Direct Inward Dialing Number on VVX Platforms, Web Proxy Auto-Discovery (WPAD), Skype for Business SILK Audio Codec, Hot Desking, Common Area Phone User, BToE Widget, Enhancements to Manual Pairing of Phone using BToE.</p>
5.6.1	December 2017	This release includes important field fixes.
5.6.0	July 2017	<p>This release includes support for the following features:</p> <p><b>Open SIP Enhancements</b></p> <p>This release introduced support for FIPS 140-2 Compliance Support, Two-Way Active Measurement Protocol support, Caller ID Display from the SIP Invite, BroadSoft Server-Based Call Waiting, Call Line Identification, BroadSoft Server-Based Redial, Remote Party Disconnect Alert Tone, Support for Siren 7 Audio Codec.</p> <p>The BroadSoft Directory now includes the following new directories:</p> <ul style="list-style-type: none"> <li>• Group and Group Common Directory</li> <li>• Enterprise Common Directory</li> <li>• Personal Directory</li> </ul> <p><b>Skype for Business Enhancements</b></p> <p>This release introduced support for Dial Plan Normalization, Multiple Emergency Number Dial Plan, Skype for Business User Interface Enhancements, Skype for Business Conference Enhancements, Device Lock Enhancements, Profile Picture on Device Lock Screen, Secure Single Sign-On With Third-Party Supporting Solutions, Safe Transfer for Boss-Admin Enhancements, and Busy Options for Incoming Calls.</p> <p><b>VVX D60 Enhancements</b></p> <p>This release introduced support for FLK Support in VVX Business Media Phone with VVX D60, Maximum Number of Handset Registrations, VVX D60 Base Station Pairing Permissions, Mac Address Pairing with VVX D60 Base Station, Continuous Attempt to Re-pair with a VVX D60 Base Station, and VVX D60 Call Handoff.</p>
5.5.3	September 2017	This release includes important field fixes.

<i>Release</i>	<i>Release Date</i>	<i>Features</i>
5.5.2	May 2017	<p>This release includes the following features and field fixes:</p> <ul style="list-style-type: none"> <li>• Enterprise Directory Default Search</li> <li>• Registration Line Address in Status Bar</li> <li>• BroadWorks Anywhere EFK for Soft Keys</li> <li>• Hide Contact Directory and Favorites</li> <li>• Personal Directory</li> <li>• BSFT Server Based Call Logs</li> <li>• New Call Forwarding Icons</li> <li>• Updated Do Not Disturb Icon</li> <li>• Expanded Support for USB Headsets</li> <li>• Support Added for CDP in VVX D60 Base Station</li> <li>• ALLOW Header in 18x Provisional Responses</li> <li>• Improved BToE device lock</li> </ul>
5.5.1	September 2016	<p>This release adds enhancements for the distribution list, QoE, device lock, Polycom BToE manual pairing, user log upload, updated UI for VVX 500 and 600, unified contact store, web sign-in for online deployments.</p>
5.5.0	June 2016	<p>This release introduced support for BroadSoft Executive Assistant and Flexible Seating, TR-069, the 3GPP Technical Specification, the IPV6 protocol, Off-hook Call Status control, ability to lock the web configuration utility after failed login attempts, and user interface enhancements.</p>
5.4.3	February 2016	<p>This release introduced the Polycom VVX D60 Wireless Handset and VVX D60 Base Station.</p>
5.4.1	December 2015	<p>This release includes support for the following features:</p> <ul style="list-style-type: none"> <li>• Introduced the Polycom VVX 301/311, 401/411, 501, and 601 business media phones.</li> <li>• Flexible line key customization for Skype for Business (EFLK)</li> <li>• Master Key Identifiers (MKI)</li> <li>• Shared Line appearance on Lync</li> <li>• BToE for Windows 10</li> <li>• Smart Search for Lync ABS</li> <li>• Support for simplified Chinese font on VVX 101</li> </ul>
5.4.0A	September 2015	<p>This release includes support for the following features:</p> <ul style="list-style-type: none"> <li>• Microsoft Office 365 and Skype for Business Online</li> <li>• Office365 and Skype for Business Provisioning and Manageability</li> <li>• Time and Date Initial Setup</li> </ul>

---

<i>Release</i>	<i>Release Date</i>	<i>Features</i>
5.4.0	May 2015	Added support for Alcatel-Lucent CTS features including: <ul style="list-style-type: none"><li>• Advanced Conference</li><li>• Shared Call Appearance with Bridge In</li><li>• Visitor Desk Phone</li><li>• This release also includes support for the following features:<ul style="list-style-type: none"><li>• Barge In on Busy Lamp Field Lines</li><li>• DTMF Relay</li><li>• SIP Instance</li><li>• Comfort Noise</li><li>• Opus Codec</li><li>• DNS Server Address Override</li><li>• Global Directory Synchronization</li><li>• Basic Menu Lock</li></ul></li><li>• Additional features including user interface improvements and resolved known issues.</li></ul>
5.3.0	March 2015	Includes support for several Lync, BroadSoft, and Open SIP features.

---

## Language Support

The VVX phone user interface includes native support for the following languages:

- Arabic, UAE
- Chinese, Traditional
- Chinese, Simplified
- Danish, Denmark
- Dutch, Netherlands
- English, Canada
- English, United Kingdom
- English, United States
- French, Canada
- French, France
- German, Germany
- Italian, Italy
- Japanese, Japan
- Korean, Korea
- Norwegian, Norway
- Polish, Poland
- Portuguese, Brazil
- Russian, Russia

- Slovenian, Slovenia
- Spanish, Spain
- Swedish, Sweden

## Security Updates

Please refer to the [Polycom Security Center](#) for information about known and resolved security vulnerabilities.

## Resolved Issues

The following table lists the resolved issues in UC Software 5.9.1.

### Resolved Issues in UC Software 5.9.1

<i>Category</i>	<i>Issue No.</i>	<i>Description</i>
General	EN-111322	Rest API management returns an incorrect value for the variable packetsExpected.
Network	EN-113463	VVX phones fail to get the IP address on correct VLAN after a network switch reboot.
Reports	EN-116609 EN-116846	Incorrect packet loss and Mean Opinion Score (MOS) is reported during SIP publish.

## Known Issues

This section lists the known issues and suggested workarounds for this release and previous releases.



These release notes do not provide a complete listing of all known issues that are included in the software. Issues not expected to significantly impact customers with standard voice and video conferencing environments may not be included. In addition, the information in these release notes is provided as-is at the time of release and is subject to change without notice.

### Known Issues

<i>Category</i>	<i>Issue ID</i>	<i>Release</i>	<i>Description</i>	<i>Workaround</i>
Audio	EN-113674	5.9.0	When you place a call from a VVX D60 handset to a remote phone, there may be choppy audio.	No workaround
Calling	EN-100534	5.9.0	VVX media phones can't send voicemail to an offline user who has enabled forwarding to PSTN.	Set the ring back timer accordingly.

<i>Category</i>	<i>Issue ID</i>	<i>Release</i>	<i>Description</i>	<i>Workaround</i>
Calling	EN-59245	5.6.1	When you place an outgoing call from the call log, the VVX D60 handset always takes the default line (1st line).	No workaround
Calling	EN-59872	5.9.0	In an intercom call between two VVX D60 handsets, when the first handset answers an incoming call, the second VVX D60 handset is unable to resume the on-hold intercom call.	No workaround
Call Management	EN-111696	5.9.0	If you change the number of lines keys during an active call when a VVX phone is paired with a VVX D60 Base station, the lines don't display.	Do not change line keys in an active call.
Device Management	EN-116169	5.9.1	VVX phones fail to pair with VVX D60 base station after changing the VLAN.	Disconnect and re-connect the ethernet cable on the VVX D60 base station.
General	EN-108973	5.9.0	When you execute a packet capture command from the cloud, libPcap occasionally doesn't start the packet capture.	Resend the start packet capture command.
General	EN-103119	5.9.0	There are volume control synchronization issues between VVX phones and the Plantronics Black wire 5220 series USB-A headset.	No workaround
Network	EN-108646	5.9.0	Polycom VVX 500 and 600 phones don't support video calls on STUN networks.	No workaround
Network	EN-117315	5.9.1	VVX101 initiates DHCPv6 process twice (releases IP and gets it again) in IPv6 mode when switch port setting is changed from voice VLAN in which DHCP services are not running to data VLAN.	No workaround

---

# Updates to Previous Software Releases

This section describes the new features and enhancements to previous UC Software releases.

## ***What's New in Polycom UC Software 5.9.0***

Polycom Unified Communications (UC) Software 5.9.0 is a release for Open SIP and Skype for Business deployments. These release notes provide important information on software updates, phone features, and known issues.

## ***Future Feature Releases for VVX Business Media Phones***

With the end of sale of some models of VVX business media phones, the following phone models will no longer receive new features:

- VVX 300/310
- VVX 400/410
- VVX 500
- VVX 600
- VVX 1500

As a result, UC Software 5.9.0 will be the last release to contain significant feature development for these models. Future major feature releases will not include images to support these models. In line with the Polycom End of Life policy, Polycom will continue to provide bug fixes in maintenance and patch releases on the UC Software 5.9.x stream. For details, see the [Polycom End of Life Policy](#).

The following VVX phone models will continue to receive feature releases:

- VVX 101/201
- VVX 150
- VVX 250
- VVX 301/311
- VVX 350
- VVX 401/411
- VVX 450
- VVX 501
- VVX 601

Plantronics headsets are compatible on VVX phones. To know compatibility list, refer [Plantronics Compatibility Guide](#).

Polycom UC Software 5.9.0 includes the following new features and enhancements:

- [Session Traversal Utilities for NAT \(STUN\)](#)

- 
- [Device Analytics Support for PDMS-SP](#)
  - [Multilevel Precedence and Preemption \(MLPP\) for Assured Services - Session Initiation Protocol \(AS-SIP\) On Shared Lines](#)
  - [Support for H.264 Packetization Mode 1 and H.264 Constrained Baseline Profile](#)
  - [Enhanced Busy Lamp Field \(BLF\)](#)
  - [Busy Lamp Field Hold Alerting](#)
  - [Busy Lamp Field\(BLF\) Spontaneous Call Appearance on Per BLF Basis](#)
  - [Enhanced Feature Key Macro Actions](#)
  - [Retrieve Logs from Support Information Package Page in the Web Configuration Utility](#)
  - [Simple Certificate Enrollment Protocol](#)
  - [Privacy for Call Logs and Contacts](#)
  - [Enhancement to Wireless Network Connectivity](#)
  - [Call Hold Timer](#)
  - [GZIP Encoding of SIP INFO Messages](#)
  - [Enhanced Boss-Admin for VVX Phones](#)
  - [Web Sign In for Skype for Business On-Premise Deployment](#)

## ***Session Traversal Utilities for NAT (STUN)***

Polycom UC Software supports Session Traversal Utilities for NAT (STUN), a network protocol used in NAT traversal for real-time IP communications, such as voice, video, and messaging. STUN service is provided using UDP. STUN using TCP or TLS is not available.

You can configure the phone to act as a STUN client to send a request to the STUN server to discover the public IP and port(s). You can also configure the phone to send keep-alive messages to refresh NAT bindings.

## ***Device Analytics Support for PDMS-SP***

Polycom introduces device analytics to enable and configure your phone to provide details on many aspects of the phone's system and usages such as network stats, feature usage, memory and CPU, SIP service state, and connected peripherals.

A Polycom Cloud Services account is required to access this analytics. For more information, refer <https://console.plcm.cloud>.

---

## ***Multilevel Precedence and Preemption (MLPP) for Assured Services - Session Initiation Protocol (AS-SIP) On Shared Lines***

Multilevel Precedence and Preemption (MLPP) enables you to configure a precedence level for outgoing calls. Polycom implements MLPP in accordance with the standards set by Assured Services for Session Initiation Protocol (AS-SIP).

Higher precedence calls preempt – and thereby end - active calls with a lower precedence level. When an active call is preempted, the phone plays a preemption tone and displays a preemption screen. Polycom now provides the capability for shared lines when operating in a Ribbon environment.

## ***Support for H.264 Packetization Mode 1 and H.264 Constrained Baseline Profile***

VVX business media phones support H.264 Packetization Mode 1 for incoming and outgoing video calls. Packetization Mode 1 enables high resolution video by allowing media packets to be fragmented during transport.

VVX business media phones also support H.264 constrained base Profile which enables to send and receive calls to IR94 capable devices.

## ***Enhanced Busy Lamp Field (BLF)***

VVX phones supporting Broadworks Enhanced Busy Lamp Field (BLF) are now able to enable and configure new short and long key press behaviors when touching the line key for a monitored BLF user. New actions are 1-touch blind transfer or 1-touch park and retrieve.

A new preferences option in the basic settings is available when configured allowing the phone user to choose their preferred default key press action.

## ***Busy Lamp Field Hold Alerting***

VVX phones now support the Busy Lamp Field (BLF) sip.rendering state. For call control platforms that also support or allow this dialog attribute to be used. VVX phones can add display information when the monitored user places a call on hold with accompanying changes to LED behavior, key press action precedence, and an optional ringtone.

## ***Busy Lamp Field (BLF) Spontaneous Call Appearance on Per BLF Basis***

VVX phone supports Spontaneous Call Appearance property for an incoming call and incoming ringtone per Busy Lamp Field (BLF).



---

## ***Enhanced Feature Key Macro Actions***

A new macro \$Tconsult\$ is added to execute the consultative transfer functionality irrespective of default transfer type (Consultative/Blind) set on the phone.

## ***Retrieve Logs from Support Information Package Page in the Web Configuration Utility***

You can export the Support Information Package (.tar file) using Web Configuration Utility.

The support information package includes the following log files:

- .pbu file
- app log file
- boot log file
- audit log file

## ***Simple Certificate Enrollment Protocol***

The Simple Certificate Enrollment Protocol (SCEP) is a protocol that enables you to automatically enroll devices to retrieve new digital certificates or re-enroll to renew expired or expiring certificates.

This feature applies to all phones except VVX 1500 business media phones.

## ***Privacy for Call Logs and Contacts***

Your call logs and contacts you save are stored on the phone and a server. You can clear your personal history of stored call logs and contacts from the phone. You can also restrict the phone from uploading your call logs and contacts to the server.

## ***Enhancement to Wireless Network Connectivity***

You can configure the phone so that users can view the Wi-Fi menu under Basic settings. This allows users to also add a Wi-Fi network manually. Additionally, you can also configure the phone to display the Wi-Fi icon on the phone's status bar and home screen.

You can manually add a new wireless network on VVX phone from the **Basic** menu.

## ***Call Hold Timer***

Polycom VVX phones will now display the timer when an active call is put on hold. The active call timer will resume when the user retrieves the call.

`up.holdTimerDisplay.enable` parameter is used to enable or disable the hold timer display on the VVX phone.

---

## ***GZIP Encoding of SIP INFO Messages***

Polycom VVX phone sends notifications for various activities to the server in gzip format saving network bandwidth.

You can configure this feature by `voIpProt.SIP.gzipEncoding.enable` parameter that is set to 0 by default.

## ***Enhanced Boss-Admin for VVX Phones***

When using Skype for Business you can configure Enhanced Boss-Admin feature on allowing users to add and edit delegates from the phone's user interface using the contacts list.

Users can also set Call Forward or Simultaneous Call Ringing option from the phone's user interface. When Enhanced Boss-Admin delegation occurs, you can view the delegate key icon on the phone's screen.

## ***Web Sign In for Skype for Business On-Premise Deployment***

Polycom UC Software 5.9.0 allows users to sign in to Skype for Business client on VVX phones. Web Sign In enables users to securely log in to Skype for Business from the phone using a computer web browser or mobile device browser. Users can sign in concurrently to a maximum of eight devices by default. When users are signed in to multiple devices and sign out from one device, users remain signed in to all other devices.



Web Sign In for Skype for Business server support requires Hybrid Modern Authentication (HMA) to be enabled. To use the capability of HMA with Skype for Business On-premise AD should be federated with Azure AD. For more information about Hybrid Modern Authentication (HMA), refer [Hybrid Modern Authentication for Skype for Business](#).

Common Area phone (CAP) feature is not supported for Web Sign In for Skype for Business On-Premises.



Polycom VVX 250, 350, and 450 business IP phones support on-premises deployments only.

## ***Configuration File Enhancements***

The following table lists configuration file enhancements that include new or changed parameters for the Polycom UC Software 5.9.0 release. For more information on using configuration parameters to enable or disable features, see the latest *Polycom UC Software Administrator Guide* for your release, available on [Latest Polycom UC Software Release](#).

---

**Configuration File Enhancements for UC Software 5.9.0**

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
firewall-nat.cfg	feature.nat.stun.enabled	0 (default) - Disable the STUN feature on the phones. 1 - Enable the STUN feature on all registered Open SIP lines on a phone.	Yes
firewall-nat.cfg	nat.stun.server	Enter a STUN server IP address or domain name. Null (default)	Yes
firewall-nat.cfg	nat.stun.port	Set the server port number for all Open SIP-registered phones. 3478 (default) 1 to 65535	Yes
firewall-nat.cfg	reg.x.nat.traversal.mode	Enable or disable NAT traversal mode with STUN for signaling and media on the basis of the phone-level STUN feature. Auto (default) - Apply NAT configuration to both media and signalling per registration. Disabled - The phone does not use STUN for NAT traversal for this registration. For example, if feature.nat.stun.enabled is set to 1, and reg.x.nat.traversal.mode is set as Auto, the STUN feature is enabled for signaling and media for the registered line.	No

---

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
firewall-nat.cfg	nat.refresh.interval	Set the time interval for the phone to send NAT keep-alive packets that keep the NAT port open and the phone reachable.  30 seconds (default) - The phone sends NAT keep-alive packets that keep the NAT port open and the phone reachable.  5 - 3600 seconds	No
applications.cfg	calendar.monthView.enabled	0 (default) - Disables the <b>Month View</b> soft key.  1 - Enables the <b>Month View</b> soft key.	No
device.cfg	device.da.enabled.set	0 (default) - Do not use the device.da.enabled value.  1 - Use the device.da.enabled value.	No
device.cfg	device.da.enabled	0 (default) – Disable the device analytics feature.  1 – Enable the device analytics feature.	Yes
features.cfg	feature.obitalk.enabled	0 (default) - Disable the connection to the OBiTalk cloud.  1 - Enable the connection to the OBiTalk cloud.	Yes
features.cfg	obitalk.accountcode	Specifies the account code provided to the service provider during registration.  Null (default)  String (maximum of 256 characters).	Yes

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
new.cfg	da.supported.services	Specify the Device Analytics service to enable. all (default) Comma seperated list of below strings need to be configured (maximum of 2048 characters) sdi ni service tsid pcap log config core vqmon cdr uptimeanalytics hardwareanalytics uianalytics blf sca restart reboot resettofactory	Yes
features.cfg	attendant.callAction	Specify the call action behavior for an Active call. Dial-Pick up (default) – An active call goes on hold and dials to monitor line when you short press the monitored line keys Blind – Blind transfer an active call on the monitored line keys Park – Parks an active call on the monitored line keys. If there is already a parked call on a monitored line then it will retrieve the parked call.	No

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
features.cfg	attendant.callActionMenu.enabled	This parameter is configured to get the Attendant Call Action menu on the phone when dynamic BLF is configured on the phone.  0 (default) – <b>Attendant Call Action</b> menu will not appear on the phone.  1 - <b>Attendant Call Action</b> menu will appear on the phone.	No
features.cfg	attendant.displayHoldState.enable=1	Specifies the control of the display on the phone for BLF hold state.  0 (default) –The phone displays a busy state.  1 – The phone displays a hold state.  Note: This parameter is only applicable to static BLF.	No
features.cfg	attendant.resourceList.NUM_REPLACE_1.hold.ringer	The ringtone that plays on the phone when BLF is in a hold state.  The parameter depends on the value set for the parameter attendant.displayHoldState.enabled. If the parameter attendant.displayHoldState.enable is set to 1, use the parameter attendant.resourceList.NUM_REPLACE_1.hold.ringer  Triplet (default) – Specifies the ringtone name for the parameter ringer11.  Ringtone for BLF Hold should play for only 10 sec.	No

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
feature.cfg	ind.pattern.blfHold. step.1.state	0 – Turns off the LED indicator for BLF Hold.  1 (default) – Turns on the LED indicator for BLF Hold.	Yes
feature.cfg	ind.pattern.blfHold. step.1.duration	Specify the duration of the LED indicator for the pattern when BLF is in a hold state.  1000 (default) 0- 32767	Yes
fetaure.cfg	ind.pattern.blfHold. step.1.color	Set the color of the LED indicator for the pattern when BLF is in a hold state.  Red (default) – LED indicator turns to red when the BLF is in a hold state.  Green – LED indicator turns green when the BLF is in a hold state.	Yes
feature.cfg	ind.pattern.blfHold. step.2.state	0 (default) – Turns off the LED indicator for BLF Hold.  1– Turns on the LED indicator for BLF Hold.	Yes
feature.cfg	ind.pattern.blfHold. step.2.duration	Specify the duration of the LED indicator for the pattern when BLF is in a hold state.  1000 (default) 0 – 32767	Yes
fetaure.cfg	ind.pattern.blfHold. step.2.color	Set the color of the LED indicator for the pattern when BLF is in a hold state.  Red (default) – LED indicator turns to red when the BLF is in a hold state.  Green – LED indicator turns green when the BLF is in a hold state.	Yes

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
features.cfg	attendant.resourceList.NUM_REPLACE_1.display.spontaneousCallAppearances	<p>This parameter is applicable to Static BLF.</p> <p>Specifies spontaneous call appearance property for an incoming call.</p> <p>This parameter will override the phone level configuration parameters <code>attendant.behaviors.display.spontaneousCallAppearances.normal</code> and <code>attendant.behaviors.display.spontaneousCallAppearances.automata</code> to show or hide the call appearance property for BLF incoming call based on the resource type.</p> <p>Auto (default) – This value will use phone-level configuration depending on the BLF resource type.</p> <p>Show – This value will override phone-level configuration and show the call appearance.</p> <p>Hide – This value will override phone-level configuration and hide the call appearance.</p> <p>Note: Existing BLF ringtone will not stop if new BLF call comes.</p>	No



<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
features.cfg	attendant.resourceList.NUM_REPLACE_1.ringType	This parameter is applicable to Static BLF. Specifies incoming ringtone for each static BLF line defaultAll (default) – Specifies the ringtone type ring for the ringtone name. ringer1 - ringer 24. If no ringtone is configured for any static BLF line, then phone level incoming ringtone defined with attendant.ringType parameter will be played.	No
features.cfg	SCEP.CAFingerprint	Configure the CA certificate fingerprint to confirm the authenticity of the CA response during enrollment. null (default) 0 - 255 characters	No
features.cfg	SCEP.certPoll.retryCount	Specify the number of times to poll the SCEP server when the SCEP server returns a Certificate Enrollment Response Message with the pkiStatus set to 'pending'. 12 (default) 1 – 24	No
features.cfg	SCEP.certPoll.retryInterval	Specify the number of seconds to wait between poll attempts when the SCEP server returns a Certificate Enrollment Response Message with the pkiStatus set to 'pending'. 300 seconds (default) 300 - 3600 seconds	No

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
features.cfg	SCEP.certRenewalRetryInterval	Specify the time interval to retry certificate renewal. 86400 seconds (default) 28800 - 259200 seconds	No
features.cfg	SCEP.certRenewalThreshold	Specify the percentage of the certificate validity interval to initiate a renewal. 80 (default) 50 – 100	No
features.cfg	SCEP.challengePassword	Specify the challenge password to send with the Certificate Signing Request (CSR) when requesting a certificate. null (default) 0 - 255 characters	No
features.cfg	SCEP.csr.commonName	Specify the common name to use for CSR generation. null (default) 0 – 64	No
features.cfg	SCEP.csr.country	Specify the country name to use for CSR generation. null (default) 0 – 2	No
features.cfg	SCEP.csr.email	Specify the email address to use for CSR generation. null (default) 0 – 64	No
features.cfg	SCEP.csr.organization	Specify the organization name to use for CSR generation. null (default) 0 – 64	No

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
features.cfg	SCEP.csr.state	Specify the state name to use for CSR generation. null (default) 0 - 128 characters	No
features.cfg	SCEP.enable	0 (default) - Disable the SCEP feature. 1 - Enable the SCEP feature.	No
features.cfg	SCEP.enrollment.retryCount	Specify the number of times to retry the enrolment process in the case of enrolment failure. 12 (default) 1 – 24	No
features.cfg	SCEP.enrollment.retryInterval	Specify the time interval to retry the enrolment process. 300 seconds (default) 300 - 3600 seconds	No
features.cfg	SCEP.http.password	Specify the password that authenticates with the SCEP server. null (default) string, max 255 characters	No
features.cfg	SCEP.http.username	Specify the user name that authenticates with the SCEP server. null (default) string, max 255 characters	No
features.cfg	SCEP.url	Specify the URL of the SCEP server. null (default) 0 - 255 characters	No
features.cfg	feature.wifi.basicmenu.enable	1 (default) – The phone displays Wi-Fi menu under <b>Basic</b> settings. 0 – The phone does not display the Wi-Fi menu.	No

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
features.cfg	status.wifi.icon.enable	1 (default) – Display the Wi-Fi icon on the status bar of the phone's screen. Users can access Wi-Fi settings by selecting the Wi-Fi icon. 0 – Does not display the Wi-Fi icon on the status bar.	No
features.cfg	homeScreen.wifi.enable	1 (default) – Display the Wi-Fi icon on the phone's Home screen. 0 – Does not display Wi-Fi icon on the phone's Home screen.	No

---

video.cfg	video.profile.H264 .packetizationMode	<p>Set to control the H.264 encoding and decoding capabilities on supported VVX business media phones.</p> <p>0 (default) - Supports Single NAL unit mode.</p> <p>For Incoming calls:</p> <ul style="list-style-type: none"> <li>• If the remote endpoint supports only Non-Interleaved mode, the VVX business media phones reject the video with m line 0.</li> <li>• If the remote endpoint supports Single NAL Unit mode, then the VVX business media phones answer the incoming call with Single NAL mode.</li> </ul> <p>For Outgoing calls:</p> <ul style="list-style-type: none"> <li>• In all outgoing calls, the VVX business media phones send packetization-mode=0 in the offer.</li> </ul> <p>1 - Supports both Single NAL Unit mode and Non-Interleaved mode.</p> <p>For Incoming calls:</p> <ul style="list-style-type: none"> <li>• The VVX business media phone answers both Single NAL Unit mode and Non-Interleaved mode.</li> </ul> <p>For Outgoing calls:</p> <ul style="list-style-type: none"> <li>• The VVX business media phones send</li> </ul>	No
-----------	--	---	----

---

<i>Template</i>	<i>Parameter</i>	<i>Permitted Values</i>	<i>Change Causes Restart or Reboot</i>
		packetization-mode=0 and packetization-mode=1 in the offer.	
feature.cfg	up.enhancedbossadmin	0 (default) - Disables the Enhanced Boss-Admin feature. 1- Enables the Enhanced Boss-Admin feature.	Yes
features.cfg	up.phoneBootStatusPopupEnabled	1 (default) - Phone displays the Popups after reboot. 0 – Phone does not display any popup after reboot.	No
sip-interop.cfg	voIpProt.SIP.gzipEncoding.enable	0 (default) – Disable the Gzip encoding. Notifications will not be sent to server in gzip format 1 – Enable the Gzip encoding. Notifications will be sent to the server in gzip format	No
features.cfg	up.holdTimerDisplay.enable	0 (default) – Hold Timer will not display 1 – Hold Timer will display	No

## Security Updates

Please refer to the [Polycom Security Center](#) for information about known and resolved security vulnerabilities.

The following table contains the security updates in UC Software 5.9.0.

### Security Updates

<i>Category</i>	<i>Issue ID</i>	<i>Release</i>	<i>Description</i>
Security	EN-103735	5.9.0	Don't use basic authentication on VVX phones due to security issues.

## Resolved Issues

The following table lists the resolved issues in UC Software 5.9.0

### Resolved Issues

<i>Category</i>	<i>Issue ID</i>	<i>Description</i>
Application	EN-112576	The phone crashed during a reboot.
Application	EN-104339	VVX business media phone reboots while processing Reverse Name Lookup (RNL).
Application	EN-104422	Once you disable KeepAlive you cannot enable until you restart the phone.
Audio	EN-105156	Audio quality is bad when using the handset.
Audio	EN-111048	When audio and video is streamed from VVX phones to far end through BTOE application, the audio is choppy due to a shortage of CPU cycles.
Audio	EN-29792	In a Lync environment, the far-end occasionally hears distorted music for Music on Hold (MOH) when the call is established via TCP.
Audio	EN-94188	In a GENBAND environment, Music on Hold (MOH) doesn't play to the far end because the phone doesn't send the full codec list when holding the call.
Audio	EN-88372	There is a 5-second audio delay on the VVX phone when you resume the remote held call on the shared phone.
Calling	EN-105254	When you set the <code>feature.persistentMute.enabled</code> parameter to 1, the active call audio splits to the speaker along the handset after a PTT/Paging call.
Calling	EN-104607	DUT is sending binding request to STUN during hold and resume calls.
Calling	EN-99796	When making a point-to-point call between a VVX 1500 business media phone and an HDX system with media encryption enabled, the VVX 1500 business media phone doesn't receive audio.
Calling	EN-97739	In an intercom call between the two VVX D60 handsets, when the first handset answers an incoming call, the second VVX D60 handset is unable to resume the on-hold intercom call.
Calling	EN-97737	In a certain environment, the VVX business media phone is not able to retrieve the parked call using the BLF line key.
Calling	EN-95752	When server-based Automatic Call Distribution feature is enabled on the phone and the agent is in a call, pressing the EFK configured Unavailable soft key doesn't change the agent's state.
Calling	EN-97753	When you configure the Busy Lamp Field feature on the VVX business media phones and search for a directory via the directory soft-key, the phone returns to the Home screen.

<i>Category</i>	<i>Issue ID</i>	<i>Description</i>
Calling	EN-101429	VVX phone is unable to resume the held call during call transfer when off-hooked.
Calling	EN-97737	In a certain environment, the VVX business media phone is not able to retrieve the parked call using the BLF line key.
Call Management	EN-110627	VVX phones failed to accept the finalized peer-reflexive ICE candidates published by the far end.
Call Management	EN-108200	The VVX phone doesn't pick up the Busy Lamp Field (BLF) incoming call when the line key is pressed while the phone is off-hook.
Certificate Management	EN-107069	DUT is disclosing certificate private key and sending insecure HTTP message.
Configuration	EN-104784	VVX phones fail to open the Web Configuration Utility in the browser in Chinese due to insufficient size of the buffer to hold the Chinese Language file. The buffer size was increased to 256MB to hold large files.
Configuration	EN-101931	The SRTP status shows incorrect details on VVX 411 and 501 business media phones.
Configuration	EN-96691	Default value of parameter <code>callLists.logConsultationCalls</code> should be changed to 1.
Configuration	EN-76181	The <code>dialplan.routing.emergency.x.value</code> parameter considers value only up to 255 characters.
Configuration	EN-111457	VVX phone displays Speed Dial Keys configuration even if the phone doesn't support the feature. This is applicable to all VVX business media phones except the VVX 1500 business media phones.
Configuration	EN-98530	The <code>SwitchingFunctionDevices</code> event sends incorrect registration line details when registration address contains domain name along with registration number.
Directories/Address Books	EN-109289	The VVX expansion modules don't refresh the speed dial list after a favorite is added or removed from the phone keys.
Directories/Address Books	EN-98753	When you configure the Busy Lamp Field feature on the VVX business media phones and search for a directory via the directory soft-key, the phone returns to the Home screen.
General	EN-109713	Polycom terminates NOTIFY line to seize Bridged Line Appearance (BLA) dialog event after it gets a 500-internal error with a retry-after 3 seconds from UAS. The parameter <code>voIpProt.SIP.blaGlareHonorRetryAfter</code> was introduced to control this issue.
General	EN-108308	A 3-second timer is applied to 911 calls on VVX phones when "[2-9]11" is not at the beginning of the digit map.
General	EN-101084	Removed <code>up.onHookDialingEnabled</code> parameter from the code as this parameter is applicable only for Spectralink wireless phones.



<i>Category</i>	<i>Issue ID</i>	<i>Description</i>
General	EN-95586	VVX business media phone continues to display the Message Waiting Indicator (MWI) after reboot / de-registration even though no voicemail is available on phone.
General	EN-107207 EN-92897	Intermittently, a VVX phone doesn't register with the backup server after an outage.
General	EN-92078	VVX business media phones receive a 400-missing contact error from session border controllers (SBC) even when sending the contact header in a 200 OK for NOTIFY.
General	EN-76384	When entering the PIN code to a conference bridge, some digit plays a long tone as if it gets stuck.
General	EN-97274	VVX business media phones intermittently display LDAP error on corporate directory screen during search operations at times of peak load.
General	EN-94806	Polycom UC software upgrade fails on VVX phones while upgrading from UC software version 5.4.5 and 5.5.1 due to "Bad Image Checksum" error.
General	EN-103385	In Skype for Business environment, RGB color for VVX phones is low in UC Software 5.7.x version.
Interoperability	EN-98487	When processing SIP URLs for a Record-Route header, VVX business media phones incorrectly prepend SIP in the URL.
Localization	EN-111652	VVX phones are not translating the Inactive string to other languages other than default language.
Localization	EN-105378	DUT sending En-US as default language when inviting far-end PSTN users into a conference.
Logs	EN-95299	In a Skype for Business environment, the username and password for the Skype for Business account display in plain text in the <b>app</b> logs and sys logs.
Network	EN-107375	In a Skype for Business environment, the description is missing in Field Help for the <code>server.log.setting.enabled</code> parameter.
Network	EN-104641	VVX phones fail to get an IP address when they receive two server identifiers (Option 54) in a DHCP offer.
Network	EN-102127	VVX business media phones use an incorrect TLS version, so TLS v1.2 connections fail.
Network	EN-98838	The INVITE for Session Description Protocol (SDP) in a conference call does not include SAVP and cryptographic line details.
Network	EN-92987	When you set the <code>feature.EWSAutodiscover.enabled</code> parameter to 1, VVX business media phones don't send the WPAD PAC file request.
Network	EN-112091	DUT fails to upgrade in a remote network using NTLM authentication.

<i>Category</i>	<i>Issue ID</i>	<i>Description</i>
Network	EN-102142	Phone authentication fails for the first time when using the TLS method with Polycom certificates for 802.1x authentication.
Provisioning	EN-93405	After a factory reset, while provisioning, the VVX business media phone accepts the parameter value of <code>voIpProt.SIP.assuredService.namespace</code> as "ets" even though configured as "dsn".
Provisioning	EN-101878	VVX business media phones restrict uploading Certificate Signing Request (CSR) and CSV files to the provisioning server root directory which causes RealPresence Resource Manager provisioning server failure.
Shared Lines	EN-104744	In VVX business media phones, the call is being answered on the headset when trying to pick up the held Multiple Appearance Directory Number (MADN) call on the remote shared device using the handset.
Security	EN-102441	When you enable the Device lock feature for the guest user, the phone asks to set a PIN lock.
Security	EN-95756	VVX business media phones don't support the NTLM v2 mechanism with the down-level format.
User Interface	EN-104782	VVX business media phones don't send any error response when the phone is in an idle state and receives an INVITE with replace header.
User Interface	EN-104591	Headset volume is increasing while switching between headset and handset.
User Interface	EN-101057	The VVX business media phone web UI help text for the <code>msg.bypassInstantMessage</code> parameter displays incorrect information.
User Interface	EN-100103	While using handsfree, headset or lifting handset to initiate a call, the idle display screensaver continues to stay on VVX business IP phone's screen.
User Interface	EN-99550	The brightness/ contrast level on Expansion Modules (EMs) connected to VVX 601 business media phone is lower when compared to EMs connected to VVX 600 business media phone.
User Interface	EN-93448	VVX business media phone is unable to display Unicode text having Armenian characters.
User Interface	EN-93031	While inviting a participant to the conference, the Reverse Name Lookup fails to continue with the next source when the display name is not received in SIP signaling.
User Interface	EN-92639	When "P-Asserted-Identity" in a 200 OK response doesn't have a display name, the phone doesn't display the caller ID details for an incoming call during call pick-up.
User Interface	EN-79960	When you connect an unsupported USB device to a VVX business IP phone, the phone doesn't display the rear USB port's power alert pop-up.
User Interface	EN-97749	On VVX business media phones, the call center queue status notification menu doesn't close automatically after 30 seconds.

---

<i>Category</i>	<i>Issue ID</i>	<i>Description</i>
User Interface	EN-97248	While playing video on an idle microbrowser, VVX 501 and 601 business media phones don't display incoming calls.
User Interface	EN-96709	During failover/ failback, the phone resets the SIP Open Programmable Interface (SOPI) subscription and phone loses speed dial and directory.
General	EN-100838	VVX business media phone does not increment the Cseq value in the PRACK message in call forking.
User Interface	EN-100910	EagleEye Mini Camera does not publish privacy report which causes VVX phones to show the wrong LED.

---

## Get Help

For more information about installing, configuring, and administering Polycom products, refer to [Polycom Support](#).

For information about Polycom partner solutions, see [Polycom Global Strategic Partner Solutions](#).

## *The Polycom Community*

The [Polycom Community](#) gives you access to the latest developer and support information. Participate in discussion forums to share ideas and solve problems with your colleagues. To register with the Polycom Community, create a Polycom online account. When logged in, you can access Polycom support personnel and participate in developer and support forums to find the latest information on hardware, software, and partner solutions topics.

# Copyright and Trademark Information

Copyright© 2019, Polycom, Inc. All rights reserved. No part of this document may be reproduced, translated into another language or format, or transmitted in any form or by any means, electronic or mechanical, for any purpose, without the express written permission of Polycom, Inc.

6001 America Center Drive  
San Jose, CA 95002  
USA

## Trademarks

Polycom®, the Polycom logo and the names and marks associated with Polycom products are trademarks and/or service marks of Polycom, Inc. and are registered and/or common law marks in the United States and various other countries.



All other trademarks are the property of their respective owners. No portion hereof may be reproduced or transmitted in any form or by any means, for any purpose other than the recipient's personal use, without the express written permission of Polycom.

## Disclaimer

While Polycom uses reasonable efforts to include accurate and up-to-date information in this document, Polycom makes no warranties or representations as to its accuracy. Polycom assumes no liability or responsibility for any typographical or other errors or omissions in the content of this document.

## Limitation of Liability

Polycom and/or its respective suppliers make no representations about the suitability of the information contained in this document for any purpose. Information is provided "as is" without warranty of any kind and is subject to change without notice. The entire risk arising out of its use remains with the recipient. In no event shall Polycom and/or its respective suppliers be liable for any direct, consequential, incidental, special, punitive or other damages whatsoever (including without limitation, damages for loss of business profits, business interruption, or loss of business information), even if Polycom has been advised of the possibility of such damages.

## End User License Agreement

BY USING THIS PRODUCT, YOU ARE AGREEING TO THE TERMS OF THE END USER LICENSE AGREEMENT (EULA) AT <http://documents.polycom.com/indexes/licenses>. IF YOU DO NOT AGREE TO THE TERMS OF THE EULA, DO NOT USE THE PRODUCT, AND YOU MAY RETURN IT IN THE ORIGINAL PACKAGING TO THE SELLER FROM WHOM YOU PURCHASED THE PRODUCT.

## Patent Information

The accompanying product may be protected by one or more U.S. and foreign patents and/or pending patent applications held by Polycom, Inc.

## Open Source Software Used in this Product

This product may contain open source software. You may receive the open source software from Polycom up to three (3) years after the distribution date of the applicable product or software at a charge not greater than the cost to Polycom of shipping or distributing the software to you. To receive software information, as well as the open source software code used in this product, contact Polycom by email at [OpenSourceVideo@polycom.com](mailto:OpenSourceVideo@polycom.com).

## Customer Feedback

We are striving to improve our documentation quality and we appreciate your feedback. Email your opinions and comments to [DocumentationFeedback@polycom.com](mailto:DocumentationFeedback@polycom.com).

## Polycom Support

Visit [Polycom Support](#) for End User License Agreements, software downloads, product documents, product licenses, troubleshooting tips, service requests, and more.