

Technical Bulletin CS-08-05

SpectraLink 8020/8030 TFTP Download Master



Problem

SpectraLink 8020/8030 Wireless Telephones will not utilize the TFTP Download Master configuration in a SpectraLink 8000 Telephony Gateway.

System Affected

SpectraLink 8020/8030 SRP Wireless Telephones
SpectraLink 8000 Telephony Gateway

Description

When using SpectraLink 8020/8030 Wireless Telephones in an SRP based system, the configuration in the SpectraLink 8000 Telephony Gateway for TFTP Download Master is ignored by the 8000 series wireless phone.

Resolution

In order to use TFTP for software updates you must either configure the 8020/8030 Wireless Telephone with the TFTP server IP address statically or via DHCP option 66 only.

The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of, Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.

Effective Date: 03/27/08