

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.7.5.746
Released File: OVA, ISO, BIN, Upgrade File
Release Date: September 7, 2018

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5.1 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-101272	Stability	RMX rebooted due to switchttpd process core dump resulting in call disconnections
EN-99871	General	Failed to add Conference IVR Service during RMX 1800 upgrade.
EN-99939	General	Address Book disappeared from RMX Manager
EN-101205	General	SIP registration for meeting rooms failed after RMX reboot resulting in loss of their Microsoft Skype presence.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Installation Notes and Rollback Considerations

For information on installation and rollback considerations, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.