

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.7.5.776
Released File: OVA, ISO, BIN, Upgrade File
Release Date: November 30, 2018
Part Number: N/A

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5.2 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-113765	Video	Inconsistent video resolution observed during ongoing conference.
EN-113101	General	An active major alarm "'No connection with Rtmlsdn' appeared during the call.
EN-112312	General	ICE candidates were being added in the initial invite irrespective of ICE enabled or not.
EN-112100	Stability	RMX automatically rebooted during ongoing conference.
EN-110881	General	Removal of DTMF codes configuration was not allowed after RMX upgrade.
EN-110877	Video	Frozen image was seen by VMR user in the ongoing call.
EN-94432	Stability	Media Card crash observed in RMX.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Installation Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Rollback Considerations

For information on rollbacks, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.