

# Patch Release Notes

## Polycom® RealPresence® Collaboration Server

---

**Build ID:** 8.7.5.854  
**Released File:** OVA, ISO, BIN, Upgrade File  
**Release Date:** June 13, 2019

### Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5.5.1 release.

| <i>Issue ID</i> | <i>Category</i> | <i>Description</i>  |
|-----------------|-----------------|---|
| EN-131682       | Video           | Video freeze observed for some seconds due to packet loss during a conference.                                    |
| EN-130437       | Content         | Multiple participants did not receive content during connect/disconnect load execution call.                      |
| EN-130785       | General         | PCM menu pop-up option did not appear at endpoint when DTMF code "##" was pressed during a call.                  |
| EN-135907       | Stability       | Multiple core dumps occurred leading to RMX 1800 reboot, causing all active calls to drop.                        |
| EN-136531       | Stability       | Siptask core dump occurred causing all active calls to drop.  |
| EN-134679       | General         | H323 call setup event is not recorded in CDR for H.323 calls.   |
| EN-131424       | Stability       | Media card crash observed on RMX 2000 causing GS500 to drop from the conference call.                             |
| EN-116938       | Stability       | Softblade content did not work during RealConnect call due to multiple core observed on blade side after upgrade. |
| EN-137969       | General         | ICE Manager did not start sometimes, making user unable to get the AFE logs.                                      |
| EN-138970       | Security        | TLS 1.0 can't be turned off for RMX Management port .   |
| EN-131479       | General         | MFA coredump observed on RMX 4000 during load testing, with no impact to ongoing service.                         |
| EN-130644       | Stability       | Media card reboot occurred causing MCU to reboot.   |
| EN-134691       | Stability       | Cascade link connected in faulty state with no video when two SVC participants join VMRs on different bridge.     |

---

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

## Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.5 Release Notes* and *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

## Installation and Upgrade Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.7.5 Release Notes*.