

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.7.5.891
Released File: OVA, ISO, BIN, Upgrade File
Release Date: Jan 14th, 2020

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5.8 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-154665	Stability	RealPresence Desktop disconnected from ongoing conference as RMX was unable to encode the Cyrillic characters present in the VMR username.
EN-162474	Content	Microsoft Skype for Business participants were unable to share content as logs were not getting removed periodically and leading to softblade disk size too full.
EN-158465	Video	Poor video quality observed on Cisco Webex RoomKit as content was sent on people video channel.
EN-157860	Stability	Multiple media card reboots observed after the RMX upgrade causing active calls to drop.
EN-140131	Stability	Poly RealConnect calls get disconnected intermittently.
EN-157778	Stability	ConfParty core observed causing the RMX to reboot.
EN-163221	Stability	Media card reboot observed during DSP recovery causing active calls to drop.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites, Installation, Upgrade and Configuration Considerations

For information on prerequisites, installation, upgrade and configuration, please refer to the *Poly RealPresence Collaboration Server v8.7.5 Release Notes* and *Poly RealPresence Collaboration Server v8.7.1 Administrator Guide*.