

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.8.0.475
Released File: OVA, ISO, BIN, Upgrade File
Release Date: March 18, 2019
Part Number: N/A

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.8.0.1 release.

| <i>Issue ID</i> | <i>Category</i> | <i>Description</i> |
|-----------------|-----------------|--|
| EN-124170 | Stability | Media Recovery alarm observed on RealPresence Collaboration Server, Virtual Edition. |
| EN-124167 | Stability | WebRTC wrapper core dump observed. |
| EN-123857 | Licensing | Incoming calls were rejected due to a token mismatch issue for a Clariti licensed RealPresence Collaboration Server. |
| EN-123052 | Stability | RMX stopped accepting Skype for Business calls. |
| EN-121608 | Audio | Popping noise observed during ongoing conference call. |
| EN-121437 | Stability | Core dump observed during ongoing conference. |
| EN-121064 | Stability | RMX reboot observed during cascaded conferences. |
| EN-119652 | Stability | Participants got dropped from ongoing conference. |
| EN-119002 | Call Management | RMX stopped connecting RealConnect calls after upgrading. |

| <i>Issue ID</i> | <i>Category</i> | <i>Description</i> |
|-----------------|-----------------|---|
| EN-117744 | Stability | RMX reboot observed unexpectedly with error. |
| EN-117579 | Content | Content sharing period failed during ongoing meeting. |
| EN-117572 | Stability | Core dump observed. RMX rebooted automatically. |
| EN-117317 | Stability | MPMRx card-powered reboot causing dial out connectivity problem. |
| EN-116890 | Stability | ConfParty core dump observed causing RealPresence Collaboration Server, Virtual Edition to reboot |
| EN-116622 | Content | Content sharing failed for Skype for Business clients. |
| EN-116557 | Stability | RMX conference terminated when some of the participants in the conference were being removed from the conference. |
| EN-115682 | Video | Layout was not correct for an RPIS321 participant. |
| EN-109301 | Call Management | Call rate suddenly dropped while sharing content during conference call. |

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.

Installation Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.

Rollback Considerations

For information on rollbacks, please refer to the *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.