

# Patch Notes



## Polycom<sup>®</sup> DMA<sup>™</sup> 7000 System

---

**Release label:** 6.1.3\_P1

**Built on version:** Polycom DMA 7000 System v6.1.3

**Released file(s):** dma\_6.1.3.1 upgrade file for pre-6.1;  
upgrade file for 6.1.x

---

### Purpose

Patch 1 for DMA 6.1.3 (i.e. v6.1.3.1) contains code changes to address the following issues:

- ❑ DMA-14363 Garbage collection pause observed on customer's DMA.
- ❑ DMA-14330 Heap usage was growing slowly over time, engineering suspects a memory leak.
- ❑ DMA-14454 Enhancement to allow upgrade from DMA 6.1.3 to 6.1.3.1

### Prerequisites/Configuration Considerations

- Systems may have Polycom DMA 7000 v6.0.x; or v6.1.x installed

### Installation Notes

An upgrade of a non-VDM DMA to v6.1.3 is allowed when v6.0.x or v6.1.x is the installed version. A DMA must be taken out of a Supercluster in order to perform this upgrade.

1. Download the upgrade file for dma\_6.1.3.1
2. Login to DMA and navigate to Maintenance > Software Upgrade
3. Select "Upload and Upgrade" and choose the upgrade file
4. DMA processes and applies patch