



POLYCOM[®]

Release Notes

Polycom Communicator Software Version: 2.0

March 26, 2007

Polycom Inc.

1565 Barber Lane, Milpitas CA 95035, USA

www.polycom.com

This document is the property of Polycom, Inc. Any duplication, reproduction, or transmission of this document, or any of its contents, to unauthorized parties without prior written permission of Polycom, is prohibited.

Table of Contents


1. GENERAL..... 2

2. SOFTWARE FEATURES 2

3. STATUS OF ISSUES RESOLVED/PENDING IN THIS RELEASE 3

1. General

These release notes apply to Polycom Communicator software version 2.0. The Communicator software installation supports the installation on Windows XP (Service Pack 2). The installation creates a Polycom Communicator shortcut in the startup group; after restarting computer, Polycom Communicator will start automatically.



The above dialog box appears after starting Polycom Communicator for the first time and launching Skype using Launch key of the Polycom Communicator or Double clicking on the Polycom Communicator shortcut icon on the desktop.

Please choose “**Allow this program to use Skype**” option and click OK.

2. Software Features

Table 1 Polycom Communicator Feature Matrix – entry into QA

<u>Polycom Communicator Features</u>	<u>FCS</u>
1. Volume Up – To increase speaker volume	Y
2. Volume Down – To decrease speaker volume	Y
3. Mute – To mute microphones	Y
4. Launch – To launch Skype	Y

<u>Polycom Communicator Features</u>	<u>FCS</u>
5. Answer button – Answering incoming call	Y
6. Answer button – Dropping call	Y
7. Blinking Green LED – Incoming call or outgoing call	Y
8. Solid Green LED – Call is in progress	Y
9. Solid Red LED – Microphones are muted	Y
10. Blinking Red LED – Call is on Hold	Y
11. Diagnostics programs - To verify the operation of Speaker, Microphone, Keypad and LEDs.	Y
12. Query AEC driver whether AEC is running or stopped	Y
13. Polycom Communicator will wake up from Standby mode in case of incoming call	Y
14. Polycom Communicator UI application	Y
15. Installation package <ul style="list-style-type: none"> • Full install – installation on a new PC with no prior Polycom Communicator software. Installs Application, Drivers. Transfers Firmware Upgrade.exe in the appropriate folder structure but does not install it.	Y
16. Changes from previous release: <ul style="list-style-type: none"> • “Register Your Product” link on Polycom Communicator home page is removed. • The installation path has been changed to “C:\Program Files\Polycom\Communicator_for_skype”. • Installation of this version uninstalls any previous versions of Polycom Communicator. 	Y

3. Major issues still pending in this release

Major bugs/Issues not yet fixed in this release of software. These are targeted to be fixed in future software release.

- Polycom Communicator 2.0 works on Windows XP Media - **Status – Not fixed.**
- Polycom Communicator 2.0 works on Windows XP on Sony Vaio - **Status – Not fixed.**

Note: The bug scenarios above are being tested with Sony Notebook VAIO VGN-FE21S with XP Media Center Edition.

- Polycom Communicator 2.0 does not work on Windows Vista OS at this time. – **Target – Vista Support in the Q4’07 timeframe**