

Technical Bulletin CS-08-08

SpectraLink WTO201 Design Change



Problem

The swivel clips for the SpectraLink 6020 and 8020/8030 Wireless Telephones have a new design.

System Affected

SpectraLink WTO201

Description

The swivel belt clip for the SpectraLink 6020 and 8020/8030 Wireless Handsets was changed slightly. While the functionality and specifications were not altered, the size and shape of the swivel clips will differ from the previous version. The clip is also contained in the WTO150 and the PTO521 kits.

The following pictures show the physical difference between the different versions. Keep in mind that the release button is now located on the bottom of the clip as opposed to the top.

The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.

Effective Date: 5/21/08

Previous Version



Current Version



The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.