

Technical Bulletin CS-09-15

WTO201 Swivel Clip Failure - 8000 Series Wireless Phones



Problem

The Spring Lock on WTO201 Swivel Clip has been found to break or fail when extraordinary force is applied. Clip may also break if pulled out of the clip without depressing the disengagement button.

System Affected

WTO201 Swivel Clip for use on 8000 Series Wireless Phones

Description

The spring lock on WTO201 Swivel Clip has been found to break or fail during extreme use conditions or Phone is caught on obstacles while inserted in the clip. Clip may also break if Phone is pulled out of clip without depressing the disengagement button.

Resolution

The WTO205 Swivel Clip is thicker and has a Tempered Steel Spring for added strength. Its new design has a smoother and rounded shape for more comfort. Its "J" Hook design adds security.

Affected Swivel Clip #WTO201



New Swivel Clip #WTO205



The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.

Effective Date: 11/01/09