

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.7.5.738
Released File: OVA, ISO, BIN, Upgrade File
Release Date: August 17, 2018
Part Number: N/A

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5 GA release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-94200	Analytics	Analytics: Errors observed in JSON File with RMX Platform.
EN-91466	Stability	The Realconnect and audio conferences on RMX were disconnected and resumed after 10 minutes due to a error in RMX Manager.
EN-98821	General	RealPresence Mobile received loud noise after volume turned up to maximum, even when all the other endpoints were muted.
EN-91657	Stability	MPMRx powered off; RMX was not taking any new calls.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Limitations

The following table lists the issue added to the limitations specified in *Polycom RealPresence Collaboration Server 8.7.5 Release Notes*:

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-101928	Analytics	Additional reboot is required after upgrade for RPP Analytics to work on RPCS 1800

Installation Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Rollback Considerations

For information on rollbacks, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.