

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.8.0.441
Released File: OVA, ISO, BIN, Upgrade File
Release Date: December 10, 2018
Part Number: N/A

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.8.0 GA release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-113870	Stability	RMX reboot observed during ongoing conference.
EN-113097	Stability	Core dump occurred, active calls dropped during conference.
EN-112848	Stability	MediaCard crash happened, alarm related to media recovery observed.
EN-112311	General	ICE candidates were being added in the initial invite irrespective of ICE enabled or not.
EN-110882	General	Removal of DTMF codes configuration was not allowed after RMX upgrade.
EN-110876	Video	Frozen image was seen by VMR user in the ongoing call.
EN-110392	General	Invalid value in call detail record file causing interop issues.
EN-109481	General	Major voltage active alarm reported and failed to clear after normal restore of Power supply.
EN-109477	Video	RMX was not sending video to AVMCU intermittently.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.

Installation Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.

Rollback Considerations

For information on rollbacks, please refer to the *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.