

Patch Notes



Polycom[®] DMA[™] 7000 System

Release label: 6.1.2_P1

Affected version: Polycom DMA 7000 System v6.1.2

Released file(s): dma_6.1.2.1 upgrade file for pre-6.1;
upgrade file for 6.1.x; ISO file; OVA file

Purpose

Patch 1 for DMA 6.1.2 (i.e. v6.1.2.1) contains code changes to address the following issues:

- ❑ DMA-13892, DMA-13894: Fix UNIX "Poodle" vulnerability
- ❑ DMA-13938: Fix memory leak
- ❑ DMA-13934: Fix H.323 startup timing issue
- ❑ DMA-13989: isFocus attribute on Contact header caused some Lync 2010 endpoints to not have HD video
- ❑ DMA-13991: CMS GC paused system for class unloading operation
- ❑ DMA-14015: DMA MCU Reliability feature caused MCU to be busied out too soon

Prerequisites/Configuration Considerations

Systems must have Polycom DMA 7000 v5.2.x; v6.0.x; or v6.1.x installed.

Installation Notes

1. Download the upgrade file for RealPresence DMA version 6.1.2.1.
2. Login to the RealPresence DMA system and navigate to the **Maintenance > Software Upgrade** page.
3. Select **Upload and Upgrade** and choose the upgrade file.
4. The RealPresence DMA system processes and applies the patch.

© 2014 Polycom, Inc. All rights reserved. POLYCOM[®], the Polycom logo, and the names and marks associated with Polycom's products are trademarks and/or service marks of Polycom, Inc. and are registered and/or common law marks in the United States and various other countries. All other trademarks are property of their respective owners.