

Patch Notes



Polycom[®] DMA[™] 7000 System

Release label: 6.2.2_P1
Built on version: Polycom DMA 7000 System v6.2.2
Released file(s): upgrade file for pre-6.1.x; upgrade file for 6.1.x and 6.2.x

Purpose

Patch 1 for DMA 6.2.2 (i.e. v6.2.2.1) contains code changes to address the following issue:

- ❑ DMA DMA-15143 When a regular endpoint joins a MeetNow Lync conference ID, if CSS GW 1.4.1 is involved, the call and the other related links drop within 1 minute.

Prerequisites/Configuration Considerations

- Systems may have Polycom DMA 7000 v6.0.x, v6.1.x, or v6.2.x installed
- When upgrading from DMA 6.1.x or 6.2.x to 6.2.2.1, the system will not preserve the call history information. To keep this data, backup the databases, upgrade the DMAs, and then restore the databases.

Installation Notes

1. Download the upgrade file for dma_6.2.2.1
2. Login to DMA and navigate to Maintenance > Software Upgrade
3. Select "Upload and Upgrade" and choose the upgrade file
4. DMA processes and applies patch