

KIRK 3040 HANDSET

Service Codes for KIRK 3040 Handset

Some of the given codes might not be active as the level of service codes implemented is depending on the hardware & software status of the handset.

To enter a Service Code - enter the requested code and press MUTE.

- *99950* - Delete Phone Book - Redial Stack /Clip Stack - Mail Stack - All Subscriptions
- *99951* - Delete Phone Book
- *99952* - Delete Redial/Clip Stack
- *99953* - Delete Mail Stack
- *99954* - Delete all Subscriptions
- *99968* - Enable B-answer when placed in charger
- *99977* - Vibrator, buzzer and display test
- *99981* - Test Display - old type
- *99982* - Read back of software part number & edition
- *99984* - Read back of serial number to display
- *99985* - Read back of battery capacity/Voltage
- *99989* - Test Display for measuring radio performance/coverage