

Technical Bulletin CS-05-13

Handsets Displaying “Flash Config Error”



Problem

Handsets displaying “Flash Config Error”

System Affected

SpectraLink i640, e340, & h340

Description

There are times in the operation of the software when changes are made to the phone's internal configuration. These changes aren't written out to the configuration right away; instead, they are buffered and written out at a convenient time when the phone is not busy with other tasks. When the phone is powered off via the power key, the software makes sure the configuration changes are written out completely before allowing power to be removed. If the battery is removed without powering the phone off, it is possible for the phone to be in the middle of a configuration write when it loses power, and the write does not complete. This handset then displays the “Flash Config Error” because there is now incomplete information written out to the configuration of the handset.

Resolution

It is possible that this error can be cleared and the handset will continue to operate as normal. This can be done by restoring the factory defaults. When the phone displays this error, power off the phone. Power on the phone in Admin mode by holding down the RED end call button while powering on the phone. Release the GREEN power button, then the RED end call button and it will then be in the Admin mode. The only choice will be to Restore Defaults. Enter 0 and then select YES to restore defaults. After that is complete when the phone powers up again, the Error should be cleared. All of the configuration information has been cleared, so it will have to be re-entered for the phone to work on your system again.

If restoring the defaults does not clear this error, please contact your service provider for a replacement handset.

The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of, Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.

Effective Date: 04/04/08