

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.5.13.347
Released File: OVA, ISO, BIN, Upgrade File
Release Date: April 23, 2019
Part Number: N/A

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.5.13.2 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-130429	Stability	Media card rebooted causing all active calls to drop.
EN-128662	Stability	RealPresence Collaboration Server 1800 rebooted causing all active calls to drop.
EN-116250	Content	Endpoint was not able to share content during an ongoing conference.
EN-126913	Stability	RealPresence Collaboration Server 4000 rebooted following a media card reboot causing all active calls to drop
EN-120968	Content	Content sharing failed when a Polycom Group Series endpoint tried to share content during an ongoing conference.
EN-119734	Content	Multiple participants did not receive content in a conference.
EN-118653	Audio	All participants observed noise during a cascaded conference when all participants were muted and volume was set to maximum.
EN-120658	Stability	Siptask core dump occurred causing all the active SIP calls to drop.
EN-115325	Stability	Siptask terminated causing all active SIP calls to drop.
EN-120925	Content	Content got dropped during an ongoing conference.
EN-119742	Audio	Popping noise occurred during an ongoing conference.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-116605	General	RealPresence Collaboration Server reported an alert for high CPU usage of the Logger process with no impact on running conferences.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the *Release Notes* for the GA release for more complete release information.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server 8.5.13 Release Notes* and *Polycom RealPresence Collaboration Server v8.5 Administrator Guide*.

Installation and Upgrade Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.5 Release Notes*.